NEW JERSEY DEPT OF ENVIRONMENTAL PROTECTION TRENTON F/6 13/13 NATIONAL DAM SAFETY PROGRAM. LAKE AMES DAM (NJ00337). PASSAIC R-ETC(U) FEB 80 WA GUINAN DACM61-79-C-0011 AD-A087 538 FEB 80 W A GUINAN NL UNCLASSIFIED 1 or 2 40 A087 539



PASSAIC RIVER BASIN
HIBERNIA BROOK, MORRIS COUNTY
NEW JERSEY

LAKE AMES DAM NJ 00337

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

COMPY COMPLEMED TO DDC CONTAINED A
LITTORY SUMBER OF PAGES WHICH DO NOT
LODUCE LEGIBLY.

ELECT : AUG 6 1980

ROVED FOR PUBLIC RELEASE DISTRIBUTION UNLIMITED.

DEPARTMENT OF THE ARMY

Philadelphia District Corps of Engineers Philadelphia, Pennsylvania

80 8 4 090

FEBRUARY 1980 CONTROL FOR PUBLIC RELEASE.

DISTRIBUTION UNLIMITED.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMEN		READ INSTRUCTIONS BEFORE COMPLETING FOR
N. REPORT NUMBER	1 .	D. 3. RECIPIENT'S CATALOG NUMBER
NJ00337	AD-A087538	
I. TITLE (and Subsisse) Phase I Inspection Report	د مرتفق المستحدات	5. TYPE OF REPORT & PERIOD COV
National Dam Safety Program Lake Ames Dam (NJ00337)		VEN FINAL
Lake Ames Dam (NJ00337) F Morris County, New Jersey	· · · · · · · · · · · · · · · · · · ·	F. PERFORMING ORG. REPORT NUME
AUTHOR(a)	Phase I Inspecie	8. CONTRACTOR GRANI NUMBER(*)
	Kart.	/ DACW61-79-C-P011 /-
WARREN A./GUINAN		15
PERFORMING ORGANIZATION NAME AN	D ADDRESS	10. PROGRAM ELEMENT, PROJECT, T AREA & WORK UNIT NUMBERS
Anderson-Nichols 6 London Rd.		(12)
Concrod, N.J. 03301		19/
1. CONTROLLING OFFICE NAME AND ADD NJ Department of Environmen	Protection /	12. REPORT DATE
Division of Water Resources	//	Feb 280
P.O. Box CN029 Trenton, NJ 08625		13. NUMBER OF PAGES
4. MONITORING AGENCY NAME & ADDRES U.S. Army Engineer District	S(II different from Controlling Office) Ph 1 ade 1 ph 4 a	15. SECURITY CLASS. (of this report)
Custom House, 2d & Chestnut		Unclassified
Philadelphia, PA 19106		15a. DECLASSIFICATION/DOWNGRAD SCHEDULE
6. DISTRIBUTION STATEMENT (of this Rep	ort)	Accession For
Approved for public release	; distribution unlimite	d. DOC TAB
A - 1 / 1	/	Unonnounced Justification
7. Find Oak		Ву
7. DISTRIBUTION STATEMENT (of the about	The state of the s	Distribution
DISTRIBUTION STRIEMERT (OF the work	ract antered IN Diock 20, it different in	Availability Codes
		Dist. Availand/or special
		A special
8. SUPPLEMENTARY NOTES		
Copies are obtainable from	National Technical Info	rmation Service.
Springfield, Virginia 2215	1.	
9. KEY WORDS (Continue on reverse side if r	necessary and identify by block number	·)
Dams		
Embankments	National Dam Sa	
Visual Inspection Structural Analysis	Lake Ames Dam, p Seepage	New Jersey
orractural miaryors	Erosion	
ABSTRACT (Coutlinue on reverse side H m	neversery and identity by block number)	
IIIIN TOURTE CITAG VACUITO A	eoiteauri fearmanta	tion as to the dam's adequ
The inspection and evaluate	on of the dom is an area	coulbad by the Mandanat Na
The inspection and evaluation	on of the dam is as pre-	scribed by the National Da investigation includes vis
The inspection and evaluation Inspection Act, Public Law 9 Inspection, review of avails	on of the dam is as pres 92-367. The technical : able design and constru	investigation includes vis ction records, and prelimi
The inspection and evaluation Inspection Act, Public Law 9	on of the dam is as presented: 22-367. The technical sable design and construct hydrologic calculation	investigation includes vis ction records, and prelimi ns, as applicable. An

DO 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

410871

SECURITY CLASSIFICATION OF THIS PAGE(When Data Enforce)		
·		j
		i
		ì
	•	1
		ŀ
		Ī
		}
·		1
		1
		1
		- 1
		1
		ł
		I
		- 1
	\	- 1
		1
		I
		}
		ľ
		1
		- 1
		- 1
		1
		l
		1
		1
		i
		ł
		į
		Į.
		- 1
		j
		1
		ł
		1
		1
		1
		1
		į
		- 1
		1
		1

NOTICE

THIS DOCUMENT HAS BEEN REPRODUCED FROM THE BEST COPY FURNISHED BY THE SPONSORING AGENCY. ALTHOUGH IT IS RECOGNIZED THAT CERTAIN PORTIONS ARE ILLEGIBLE, IT IS BEING RELEASED IN THE INTEREST OF MAKING AVAILABLE AS MUCH INFORMATION AS POSSIBLE.



DEPARTMENT OF THE ARMY PHILADELPHIA DISTRICT, CORPS OF ENGINEERS CUSTOM HOUSE - 2 D & CHESTNUT STREETS PHILADELPHIA, PENNSYLVANIA 19106



28 JUL 1980

Honorable Brendan T. Byrne Governor of New Jersey Trenton, New Jersey 08621

Dear Governor Byrne:

Inclosed is the Phase I Inspection Report for Lake Ames Dam in Morris County, New Jersey which has been prepared under authorization of the Dam Inspection Act, Public Law 92-367. A brief assessment of the dam's condition is given in the front of the report.

Based on visual inspection, available records, calculations and past operational performance, Lake Ames Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in poor overall condition. The dam's two spillways are considered inadequate because a flow equivalent to 19 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

- a. The spillways' adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial action to ensure spillway adequacy should be initiated.
- b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to:
- (1) Investigate the seepage and standing water at the toe of the dam and design remedial or control measures, if needed.
- (2) Design and oversee repairs for eroded areas on the upstream and downstream slopes of the dam, including removal or replacement of the deteriorated concrete wall on the upstream edge of the crest of the embankment.

NAPEN-N

Honorable Brendan T. Byrne

- (3) Design and oversee procedures for removing or rehabilitating the dry stone-masonry retaining wall at the downstream toe of the embankment between the stoplog spillway and the north abutment.
- (4) Design and oversee procedures for the removal of trees and brush from the upstream slope, downstream slope, and a zone 25 feet wide at the downstream toe of the embankment, and for removal of the tree behind the stone-masonry training wall on the south side of the principal spillway discharge channel.
- (5) Design and oversee the removal and replacement of the stoplog facility.
- (6) Design and oversee the rebuilding of the spillway cap and abutments.
- c. Within six months from the date of approval of this report, the owner should establish a surveillance program for use during and immediately following periods of heavy rainfall and also a warning program to follow in case of emergency conditions.
- d. Within thirty days from the date of approval of this report, the following remedial actions should be initiated:
 - (1) Monitor the seepage at the downstream toe of the dam.
 - (2) Control trespassing on the dam to help decrease erosion.
- (3) Clear brush, logs and debris from the channels downstream of the stoplog spillway and emergency spillway and from the entrance channel to the emergency spillway.
- e. Within one year from the date of approval of this report the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

A copy of the report is being furnished to Mr. Dirk C. Hofman, New Jersey Department of Environmental Protection, the designated State Office contact for this program. Within five days of the date of this letter, a copy will also be sent to Congressman Courter of the Thirteenth District. Under the provision of the Freedom of Information Act, the inspection report will be subject to release by this office, upon request, five days after the date of this letter.

NAPEN-N Honorable Brendan T. Byrne

Additional copies of this report may be obtained from the National Technical Information Services (NTIS), Springfield, Virginia 22161 at a reasonable cost. Please allow four to six weeks from the date of this letter for NTIS to have copies of the report available.

An important aspect of the Dam Inspection Program will be the implementation of the recommendations made as a result of the inspection. We accordingly request that we be advised of proposed actions taken by the State to implement our recommendations.

Sincerely,

JAMES G. TON

Colonel, Corps of Engineers

District Engineer

fine of the

l Incl As stated

Copies furnished:
Mr. Dirk C. Hofman, P.E., Deputy Director
Division of Water Resources
N.J. Dept. of Environmental Protection
P.O. Box CN029
Trenton, NJ 08625

Mr. John O'Dowd, Acting Chief Bureau of Flood Plain Regulation Division of Water Resources N.J. Dept. of Environmental Protection P.O. Box CN029 Trenton, NJ 08625

LAKE AMES DAM (NJ00337)

CORPS OF ENGINEERS ASSESSMENT OF GENERAL CONDITIONS

This dam was inspected on 6 November 1979, by Anderson-Nichols & Co., Inc. under contract to the State of New Jersey. The State, under agreement with the U.S. Army Engineer District, Philadelphia, had this inspection performed in accordance with the National Dam Inspection Act, Public Law 92-367.

Lake Ames Dam, initially listed as a high hazard potential structure but reduced to a significant hazard potential structure as a result of this inspection, is judged to be in poor overall condition. The dam's two spillways are considered inadequate because a flow equivalent to 19 percent of the Spillway Design Flood - SDF - would cause the dam to be overtopped. (The SDF, in this instance, is one half of the Probable Maximum Flood.) To ensure adequacy of the structure, the following actions, as a minimum, are recommended:

- a. The spillways' adequacy should be determined by a qualified professional consultant engaged by the owner using more sophisticated methods, procedures, and studies within six months from the date of approval of this report. Within three months of the consultant's findings, remedial action to ensure spillway adequacy should be initiated.
- b. Within six months from the date of approval of this report, engineering studies and analyses should be performed to:
- (1) Investigate the seepage and standing water at the toe of the dam and design remedial or control measures, if needed.
- (2) Design and oversee repairs for eroded areas on the upstream and downstream slopes of the dam, including removal or replacement of the deteriorated concrete wall on the upstream edge of the crest of the embankment.
- (3) Design and oversee procedures for removing or rehabilitating the dry stone-masonry retaining wall at the downstream toe of the embankment between the stoplog spillway and the north abutment.
- (4) Design and oversee procedures for the removal of trees and brush from the upstream slope, downstream slope, and a zone 25 feet wide at the downstream toe of the embankment, and for removal of the tree behind the stone-masonry training wall on the south side of the principal spillway discharge channel.
- (5) Design and oversee the removal and replacement of the stoplog facility.
- (6) Design and oversee the rebuilding of the spillway cap and abutments.

11

- c. Within six months from the date of approval of this report, the owner should establish a surveillance program for use during and immediately following periods of heavy rainfall and also a warning program to follow in case of emergency conditions.
- d. Within thirty days from the date of approval of this report, the following remedial actions should be initiated:
 - (1) Monitor the seepage at the downstream toe of the dam.
 - (2) Control trespassing on the dam to help decrease erosion.
- (3) Clear brush, logs and debris from the channels downstream of the stoplog spillway and emergency spillway and from the entrance channel to the emergency spillway.
- e. Within one year from the date of approval of this report the owner should develop written operating procedures and a periodic maintenance plan to ensure the safety of the dam.

APPROVED: Kines The

JAMES G. TON

Colonel, Corps of Engineers

District Engineer

DATE: LO JUN SO

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lake Ames Dam

Identification No.: Fed ID No. NJ00337

State Located: New Jersey County Located: Morris

Stream: Hibernia Brook

River Basin: Passaic

Date of Inspection: November 6, 1979

ASSESSMENT OF GENERAL CONDITIONS

Lakes Ames Dam is about 45 years old and in poor condition. is small in size and classified as significant hazard. There is a major seepage at the downstream toe of the dam near the north abutment and a pool of standing water in a depression near the toe of the dam north of the stoplog spillway discharge channel. The upstream and downstream slopes of the embankment are deeply eroded adjacent to the south side of the stoplog spillway. upstream slope of the embankment is deeply eroded next to the north side of the principal spillway. Ruins of a concrete wall are visible at several locations on the upstream edge of the crest of the embankment; the concrete is badly deteriorated and the wall is broken and tilted at several locations. A dry stone-masonry wall which retains the downstream toe of the embankment between the stoplog spillway, and the north abutment bulges locally. slopes and crest of the dam are covered with varying amounts of trees, brush and grass. The combined capacity of the principal, stoplog, and emergency spillways is less than 18 percent of the selected half-PMF and is inadequate.

We recommend that the owner retain the services of a professional engineer, qualified in the design and construction of dams, to accomplish the following in the near future: investigate the seepage and standing water at the toe of the dam and design remedial or control measures, if needed; design and oversee repairs for eroded areas on the upstream and downstream slopes of the dam, including rehabilitation or replacement of the deteriorated concrete wall on the upstream edge of the crest of the embankment; design and oversee procedures for removing or rehabilitating the dry stone-masonry retaining wall at the downstream toe of the embankment between the stoplog spillway and the north abutment; design and oversee procedures for the removal of trees and brush from the upstream slope, downstream slope, and the downstream toe of the embankment, and for removal of the tree behind the stone-masonry training wall on the south side of the principal spillway discharge channel; design and oversee the removal and replacement of the stoplog structure; design and oversee the rebuilding of the spillway cap and abutments; conduct further detailed hydrologic and hydraulic analysis of the watershed, reservoir, dam and spillways to determine the need for and type of mitigating measures required.

We further recommend that, as part of operating and maintenance procedures, the owner monitor seepage at the downstream toe of the dam; control trespassing on the dam to reduce erosion; and clear brush, logs and debris from the channels downstream of the stoplog spillway and emergency spillway and from the entrance channel to the emergency spillway. These tasks should commence immediately. In the future, the owner should establish a surveillance program for use during and immediately following periods of heavy rainfall, and also, a warning program to follow in case of emergency conditions. Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.

ANDERSON-NICHOLS & COMPANY, INC.

Warren A. Guinan

Project Manager

New Jersey No. 16848

Naview a. Suman



Overview Lake Ames Dam

CONTENTS

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY REPORT LAKE AMES DAM N.J. NO. 22-27 FED ID NO. NJ00337

		Page
SECTION 1	PROJECT INFORMATION	
	1.1 General 1.2 Project Description 1.3 Pertinent Data	1 1 2
SECTION 2	ENGINEERING DATA	
	2.1 Design 2.2 Construction 2.3 Operation 2.4 Evaluation	6 6 6
SECTION 3	VISUAL INSPECTION	7
SECTION 4	OPERATIONAL PROCEDURES	
	4.1 Procedures 4.2 Maintenance of Dam 4.3 Maintenance of Operating Facilities 4.4 Warning System 4.5 Evaluation of Operational Adequacy	8 8 8 8
SECTION 5	HYDRAULIC/HYDROLOGIC	9
SECTION 6	STRUCTURAL STABILITY	11
SECTION 7	ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES	
	7.1 Assessment7.2 Recommendations/Alternative Measures	12 12
FIGURES	 Essential Project Features Location Map 	
APPENDICES	 Check List Visual Inspection Photographs Hydrologic Computations References 	

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY INSPECTION PROGRAM LAKE AMES DAMS U.S. #NJ00337-N.J. #22-27

SECTION I PROJECT INFORMATION

1.1 General

- a. Authority. Authority to perform the Phase I Safety Inspection of Lake Ames Dam was received from the State of New Jersey, Department of Environmental Protection (NJDEP), Division of Water Resources by letter dated 26 October 1979 under Contract No. FPM-39 dated 28 June 1978. This Authority was given pursuant to the National Dam Inspection Act, Public Law 92-367 and by agreement between the State and the U.S. Army Engineer District, Philadelphia. The inspection discussed herein was performed by Anderson-Nichols & Company, Inc. on 6 November 1979.
- b. <u>Purpose</u>. The purpose of the Phase I Investigation is to develop an assessment of the general conditions with respect to the safety of Lake Ames Dam and appurtenances based upon available data and visual inspection, and determine any need for emergency measures and conclude if additional studies, investigations, and analyses are necessary and warranted.

1.2 Project Description

Description of Dam and Appurtenances. Lake Ames Dam is a 9-foot high, 287-foot long earthfill and concrete dam. The crest of the embankment is approximately 20 feet wide. upstream face slopes at about 1H:1V and the slope of the downstream face varies from vertical to 4H:1V. The crest of the embankment section is grass covered. Its upstream face is covered with low shrubs and weeds while the downstream face supports shrubs, weeds, and some trees up to 18 inches in diameter. An emergency spillway is located at the extreme north end of the dam. It is 20 feet long with vertical stone abutments and a rocklined bottom which forms an uneven crest. A 4-foot long stoplog structure is located near the center of the embankment section. Its concrete walls are bridged by 5 sections of steel rail. The tailrace for the stoplog spillway is bordered by 5-foot high stone vingwalls. The extreme south end of the dam consists of a 45-foot long, 15-foot wide principal spillway. The crest is a concrete cap that sits atop a stone masonry base which forms a vertical outfall. The tailrace for the principal spillway is also bordered by 5-foot high stone-masonry walls running about 15 feet downstream from the vertical outfall. The south abutment of the dam consists of a sandy beach while the north abutment is a steep, partially wooded slope adjacent to N.J. Route 513. Essential features of the dam are given in Figure 1.

- b. Location. Lake Ames Dam is located in Morris County, New Jersey, on Hibernia Brook, which flows into Beaver Brook, a tributary of the Rockaway River. The dam is shown on U.S.G.S. Quadrangle, Dover, New Jersey, with approximate coordinates of N 40° 57.1', W 74° 30.1'. A location map has been included as Figure 2.
- c. Size Classification. Lake Ames Dam is classified as small on the basis of storage at top of dam of 197 acre-feet, which is less than 1000 acre-feet, but more than 50 acre-feet, and on the basis of structural height of 9 feet, which is less than 40 feet, in accordance with criteria given in the Recommended Guidelines for Safety Inspection of Dams.
- d. Hazard Classification. Visual inspection of the downstream area revealed one inhabited structure located about 6 feet above Hibernia Brook. The breach analysis contained herein indicates that flood stages associated with the half-PMF would reach about 4.5 feet above the sill of the structure. Also, the bridge carrying New Jersey Route 513, a frequently traveled road located about 800 feet downstream of the dam, would be inundated by about 4 feet of water. Appreciable property damage and loss of a few lives could occur. Accordingly, Lake Ames Dam is classified as Significant Hazard.
- e. Ownership. The dam is owned by the Township of Rockaway, 19 Mount Hope Road, Rockaway, New Jersey, 07866. The town engineer is Art Deluca; phone: 201/625-3700.
- f. Purpose of Dam. The dam provides recreation for the surrounding community.
- g. Design and Construction History. No information was disclosed regarding the design and construction of the original dam.
- h. Normal Operational Procedures. No operational procedures exist for Lake Ames Dam.
- i. Site Geology. No site specific geologic information (such as borings) was available at the time the dam was inspected. Information derived from a report entitled "Engineering Geology of the Northeast Corridor, Washington, DC to Boston, MA" and the Geologic Map of New Jersey (Lewis and Kummel, 1912) indicate that soils within the immediate site area consist of ground moraine overlying bedrock. Although no outcrops were observed during inspection of this dam, the previously mentioned reports indicate that the underlying bedrock consists of granitoid gneiss, with associated migmatite, granulite, amphibolite and granitic rocks of Precambrian age.

1.3 Pertinent Data

- a. Drainage Area
 - 5.3 square miles

b. Discharge at Damsite (cfs)

Maximum flood at damsite - unknown

Principal spillway capacity at top of dam - 382

Stoplog spillway capacity at top of dam - 29

Emergency spillway capacity at top of dam - 72

Total spillway capacity at top of dam - 483

Low-level outlet - not applicable

c. Elevation (ft. above NGVD)

Top of dam - 637.1

Recreation pool - 635.0

Spillway crest - 634.9

Maximum pool (PMF) - 641.6

Streambed at centerline of principal spillway - 628.7 (downstream); 633.9 (upstream)

Maximum tailwater (estimated) - 632

d. Reservoir Length (feet)

Maximum pool - 1330

Recreation pool - 1300

e. Storage (acre-feet)

Recreation pool - 155

Design surcharge (PMF) - 292

Top of dam - 197

f. Reservoir Surface Area (acres)

Top of dam - 16

Recreation pool - 14

Spillway crest - 14

g. Dam

Type - earthfill and concrete

Length - 287 feet

Height - 8 feet (hydraulic)

- 9 feet (structural)

Topwidth - 20 feet

Side slopes - upstream lH:lV

downstream varies 4H:1V to vertical

Zoning - unknown

Impervious core - unknown

Cutoff - unknown

Grout curtain - unknown

h. Principal Spillway

Type - concrete vertical

Length of weir - 45 feet

Crest elevation - 634.9 NGVD

Gates - none

Upstream channel - Lake Ames (no approach channel)

Downstream channel - Hibernia Brook

i. Emergency Spillway

Type - rock-lined bottom sloping gradually downward

Length of weir - 20 feet

Crest elevation - 635.5 (low point along crest)

Gates - none

Upstream channel - Lake Ames (no approach channel)

Downstream channel - tributary to Hibernia Brook

j. Stoplog Spillway

Type - concrete vertical

Length of weir - 4 feet

Crest elevation - 635.2 (top of debris)

Gates - none

Upstream channel - Lake Ames (no approach channel)

Downstream channel - tributary to Hibernia Brook

k. Regulating Outlets

Type - concrete stoplog structure

Length - 4 feet

Access - crest of embankment section

Regulating facilities - none; concrete stoplog structure; stoplogs have been removed.

SECTION 2 ENGINEERING DATA

2.1 Design

No plans, hydraulic or hydrologic data pertinent to Lake Ames Dam were available.

2.2 Construction

No data concerning construction of Lake Ames Dam were disclosed.

2.3 Operation

No engineering operational data were available.

2.4 Evaluation

- a. Availability. A search of the NJDEP files and contact with community officials revealed only a limited amount of recorded information.
- b. Adequacy. Because of the limited amount of recorded data available, evaluation of this dam was based solely on visual observations.
- c. Validity. Information disclosed by community officials appears to concur with that obtained by the inspection team.

SECTION 3 VISUAL INSPECTION

3.1 Findings

- A major seepage was observed at the downstream toe of the dam near the north abutment. There is also a pool of standing water in a depression near the toe of the dam north of the stoplog spillway discharge channel. The upstream and downstream slopes of the embankment are deeply eroded next to the south side of the concrete stoplog spillway structure. upstream slope of the embankment is deeply eroded next to the north side of the principal spillway. Deep erosion channels are present on the upstream side of the south abutment which is a sandy parking and access area. Minor erosion of the upstream slope has occurred at several locations due to both trespassing and wave action. An apparent remnant of a concrete wall is visible at several locations on the upstream edge of the crest of the embankment; the concrete is badly deterioriated and the wall is broken and tilted at several locations. A dry-stone-masonry wall which retains the downstream toe of the embankment between the stoplog spillway and the north abutment bulges locally and is toppled over locally. The crest of the dam is covered with coarse weeds. The upstream slope of the dam is covered with brush. The downstream slope of the dam is covered with trees, brush, and cut brush.
- b. Appurtenant Structures. Trees are growing at the entrance to the emergency spillway channel. A large tree is growing immediately behind the stone-masonry training wall on the north side of the discharge channel immediately downstream of the principal spillway. The west side of concrete capped spillway and its concrete abutments are badly cracked and deteriorated. The stoplog spillway near the center of the dam is severely deteriorated. The upstream concrete walls have collapsed into the intake channel and effectively block it. The steel stoplog supports are badly corroded. The south wall of the stoplog structure has a large hole in it through which water flows from the embankment south of the wall and into the spillway channel.
- c. Reservoir Area. The watershed above the lake is moderately sloping and wooded. There are no buildings on the shore of the lake. The slopes on the shore of the lake appear to be stable. No evidence of significant sedimentation was observed.
- d. Downstream Channel. Trees overhang the channels down-stream of the principal spillway, the stoplog spillway and the emergency spillway. In addition, there are logs, brush and debris in the discharge channel below the stoplog spillway, and there is brush growing in the discharge channel below the emergency spillway.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Procedures

No formal operational procedures for Lake Ames Dam exist.

4.2 Maintenance of Dam

No formal maintenance procedures for the dam were disclosed. From a phone conversation with the Town Engineer, Art Deluca, it was learned that "the area around the pond will be spruced up" as part of the facelifting program dealing with several recreational areas in the town.

4.3 Maintenance of Operating Facilities

No formal maintenance procedures for the operating facilities exist. The stoplog structure appears to have been undergoing decay for quite a few years.

4.4 Warning System

No warning system exists for Lake Ames Dam.

4.5 Evaluation of Operational Adequacy

Because of the lack of operation and maintenance procedures, the remedial measures described in Section 7.2 should be implemented as prescribed.

SECTION 5 HYDROLOGIC/HYDRAULIC

5.1 Evaluation of Features

- a. <u>Design Data</u>. An evaluation could not be performed because no data were disclosed.
- b. Experience Data. Investigation of the files at the NJDEP and telephone contact with the Township of Rockaway yielded no data concerning past overtopping or flood heights at Lake Ames Dam.
- c. <u>Visual Observations</u>. Erosion of the embankment section was noted adjacent to the south wall of the stoplog spillway. Water is passing through a hole in the stoplog structure concrete wall and discharging back into the spillway. The entrance to the spillway is almost completely blocked with debris. There was no visual evidence of damage to the structure caused by overtopping.
- d. Overtopping Potential. The hydraulic/hydrologic evaluation for Lake Ames Dam is based on a Spillway Design Flood (SDF) equal to one-half the Probable Maximum Flood (PMF) in accordance with the range of test floods given in the evaluation guidelines for dams classified as high hazard and small in size. The PMF was determined by application of the SCS dimensionless unit hydrograph to a 24-hour probable maximum storm of 22.7 inches. Hydrologic computations are shown in Appendix 3. The routed half-PMF peak discharge resulting from the combination of flow from sub-areas 1 & 2 (see sketch, Appendix c, p. 5/16) is 8,569 cfs.

Water will rise to a depth of 2.2 feet above the spillway crest before overtopping the low section along the dam embankment crest. Under this head, the combination of the principal, emergency, and stoplog spillways will pass a total flow of 483 cfs, which is less than the selected SDF.

Flood routing calculations indicate that Lake Ames Dam will be overtopped for about 9 hours to a maximum depth of 4.5 feet under half-PMF conditions. It is estimated that the spillways can pass less than 18 percent of the half-PMF before overtopping of the dam occurs; thus, the spillway is considered inadequate.

The dam was initially classified as significant hazard based on visual observation. A breach analysis was performed to assess the increase in downstream hazard under dam failure conditions and determine if the dam might be high hazard. The results of the breach analysis, contained in Appendix 3, show that the downstream potential for loss of life and excessive property damage is not increased under dam failure conditions. However, the analysis does indicate that heavily traveled N.J. Route 513 will

be inundated by up to 4 feet of water and that one house about 2000 feet downstream of the dam could be inundated above the first floor sill by 4.5 feet of water. Flow velocities at these locations would be very high.

SECTION 6 STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

Major seepage near the north abutment and standing water in a depression north of the stoplog spillway discharge channel are indicative of seepage through and under the dam, which, if not properly controlled, could lead to failure of the dam. Deep erosion of both the upstream and downstream slopes of the dam could result in breaching of the dam if allowed to continue. concrete wall on the upstream edge of the crest, which may have been intended to control erosion or seepage, is in such poor condition that it cannot be relied upon for either of these purposes. Local failures of the dry stone-masonry retaining wall at the downstream toe of the embankment between the stoplog spillway and the north abutment could initiate seepage and erosion problems if allowed to continue. Trees growing on the downstream slope and in the downstream toe area, and brush which is now growing on the upstream and downstream slopes and may attain treesize eventually, may cause seepage and erosion problems if a tree blows over and pulls out its roots or if a tree dies or is cut and its roots rot. Based on the visual inspection alone it is not possible to determine the character of the dam foundation or the interior of the cross section. Therefore, it is not possible to evaluate the factor of safety of the dam against slope failure. The severe deterioration of the spillway abutments and stoplog facility, if allowed to progress, could result in failure of the structure.

6.2 Design and Construction Data

No design or construction data pertinent to the structural stability of the dam were available.

6.3 Operating Records

No operating records pertinent to the structural stability of the dam were found.

6.4 Post-Construction Changes

No records pertinent to post-construction changes were disclosed.

6.5 Seismic Stability

Lake Ames Dam is located in Seismic Zone 1. According to the Recommended Guidelines, dams located in Seismic Zone 1 "may be assumed to present no hazard from earthquake provided static stability conditions are satisfactory and conventional safety margins exist". However, because no data are available concerning the engineering properties of the embankment and foundation materials for this dam or of the below-ground configuration of the concrete walls in the dam, it is not possible to make an engineering evaluation of the stability of the slopes or the factor of safety under static conditions.

SECTION 7 ASSESSMENT, RECOMMENDATIONS/REMEDIAL MEASURES

A Section of the second

Action of the Contract of the

7.1 Dam Assessment

- a. Condition. Lake Ames Dam is about 45 years old and is in poor condition.
- b. Adequacy of Information. The information available is such that the assessment of the dam must be based on the results of the visual inspection. The presence of coarse weeds on the crest of the embankment, brush on the upstream slope, and brush, trees, and piles of cut brush on the downstream slope make it impossible to inspect the dam adequately.
- c. <u>Urgency</u>. The recommendations made in 7.2 a. and 7.2 b. should be implemented by the owner as prescribed.
- d. Necessity for Additional Data/Evaluation. The information available from the visual inspection is adequate to identify the potential problems which are listed in 7.2 a. These problems require the attention of a professional engineer who will have to make additional engineering studies to design or specify remedial measures. If left unattended, the problems could lead to failure of the dam. The dam should be reinspected after the trees, brush, and weeds have been cleared from the embankment.

7.2 Recommendations/Remedial Measures


- a. Recommendations. The owner should engage a professional engineer experienced in the design and construction of dams to do the following things in the near future:
- 1. Investigate the seepage and standing water at the toe of the dam and design remedial or control measures, if needed.
- 2. Design and oversee repairs for eroded areas on the upstream and downstream slopes of the dam, including removal or replacement of the deterioriated concrete wall on the upstream edge of the crest of the embankment.
- 3. Design and oversee procedures for removing or rehabilitating the dry stone-masonry retaining wall at the down-stream toe of the embankment between the stoplog spillway and the north abutment.
- 4. Design and oversee procedures for the removal of trees and brush from the upstream slope, downstream slope, and a zone 25 feet wide at the downstream toe of the embankment, and for removal of the tree behind the stone-masonry training wall on the south side of the principal spillway discharge channel.


- 5. Design and oversee the removal and replacement of the stoplog facility.
- 6. Design and oversee the rebuilding of the spillway cap and abutments.
- 7. Conduct further detailed hydrologic and hydraulic analyses for the watershed, reservoir, dam and spillways to determine the need for and type of mitigating measures required.
- b. Operating and Maintenance Procedures. The owner should undertake the following things imendiately:
 - 1. Monitor the seepage at the downstream toe of the dam.
 - 2. Control trespassing on the dam to reduce erosion.
- 3. Clear brush, logs and debris from the channels downstream of the stoplog spillway and emergency spillway and from the entrance channel to the emergency spillway.

The Owner should undertake the following things in the near future:

- 1. Establish a surveillance porgram for use during and immediately following periods of heavy rainfall.
- 2. Establish a warning program to follow in case of emergency conditions.


Within one year from the date of approval of this report, the owner should develop written operating procedures and a periodic maintenance plan to insure the safety of the dam.






SECTIONS C-C & D-D

BEAC



ELEVATION B-B



PLAN

Anderson-Nichols 8 Co, Inc
CONCORD

NEW HAMPSHIRE

CONCORD

NATIONAL PROGRAM OF INSPECTION OF NON-FED. DAMS

LAKE AMES DAM

HIBERNIA BROOK

SCALE NOT TO SCALE
DATE JANUARY 1980

FIGURE -



APPENDIX 1

CHECK LIST

VISUAL INSPECTION

LAKE AMES DAM

Check List Visual Inspection Phase l

į.

NJDEP		NGVD
Coordinators N.	48 ⁰ F	of Inspection 629.3
State NJ	Temperature	ailwater at Time
Morris	Weather cool, cloudy	535.0 NGVD T
County	- 1	nspection
Name Dam Lake Ames Dam	Date(s) Inspection Nov. 6, 1979	Pool Elevation at Time of Inspection 635.0 NGVD Tailwater at Time of Inspection 629.3

Inspection Personnel:

Ronald Hirschfeld		
Warren Guinan	Stephen Gilman	Kenneth Stuart

Gilman/Hirschfeld Recorder

1-1

CONCRETE/MASONRY DAMS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES	Upstream concrete wall visible only partial length of dam. Top of wall is badly deteriorated and spalled; many areas of cracking.	Rebuild upstream concrete wall.
STRUCTURAL CRACKING		
VERTICAL AND HORIZONTAL ALIGNMENT		
MONOLITH JOINTS		

None visible.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	Stone retaining wall at toe of dam between left abutment and stoplog spillway is bulging locally and has toppled over locally.	Rebuild downstream toe of dam.
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Erosion at meny localized sections of upstream slope due to wave action and trespassing.	Repair eroded areas. Clear brush now growing on upstream slope. Establish grassy vegetation and place erosion protection.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Good.	

No riprap. Apparent remnant of a concrete wall badly deteriorated and toppled over locally, along upstream edge of crest from left abutment to stoplog spillway.

See note under "Sloughing or Erosion..." above.

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
RAILINGS	No railings.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Major erosion at right side of stoplog spillway and left side of principal spillway.	Repair erosion next to principal and stoplog spillway structure.
ANY NOTICEABLE SEEPAGE	Major seepage near toe of dam near left abutment. Water standing in depression downstream of dam to right of stoplog spillway channel.	Engage engineer to investigate source of seepage and to design appropriate remedial measures.
STAFF GAGE AND RECORDER	None observed.	
DRAINS	None observed.	

UNGATED SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS Concrete capped stone masonry; concrete apron	REMARKS OR RECOMMENDATIONS Rebuild concrete spillway and
CONCRETE WEIR	badly cracked and spalled. Middle construction joint is eroded. Right abutment is badly cracked, spalled, and undermined. Top is tipped approximately 2". Left abutment badly undermined and tipped. Large piece of concrete wall missing at upstream end of abutment.	training wall.
APPROACH CIIANNEL	Wide and unobstructed.	
DISCHARGE CHANNEL	Trees overhang channel. Channel bottom covered with boulders.	Clear trees and brush on either side of channel to prevent channel blockage. Maintain cleared area free of brush.

GATED SPILLWAY

(STOPLOG SPILLWAY)

REMARKS OR RECOMMENDATIONS	Remove and replace stoplog spillway. mel		Clear channel of debris from dam to highway bridge downstream. Clear trees and brush on either side of channel for a distance downstream from dam. Maintain cleared areas free of brush.		iorated. Remove and replace stoplog spillway.
OBSERVATIONS	Both walls of channel are badly eroded and spalled. Concrete core wall near channel has large hole in it where water is discharging. Steel rails across channel are rusted. Upstream end of channel has collapsed, blocking some flow area.	Debris filled.	Logs, brush, debris and uprooted trees clog channel at several locations.	None.	Stoplogs - visible portions badly deteriorated.
VISUAL EXAMINATION OF	CONCRETE WALLS	APPROACH CHANNEL	DISCHARGE CHANNEL	BRIDGE AND PIERS	GATES AND OPERATION

EMERGENCY SPILLWAY

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
WEIR	6-12 inch diameter rocks resting on soil. Some weeds.	No action required.
APPROACH CHANNEL	Wide and unobstructed.	
DISCHARGE CHANNEL	Rocks and some weeds and brush. 2' high stone masonry walls form sides.	
BRIDGE AND PIERS OVER SPILLWAY	None.	

INSTRUMENTATION

VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
MONUMENTATION/SURVEYS	None observed.	-
OBSERVATION WELLS	None observed.	
WEIRS	None observed.	
PIEZOMETERS	None observed.	
ОТНЕR	None observed.	

RESERVOIR

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	Moderately sloping and wooded.	
SEDIMENTATION	No evidence of significant sedimentation observed.	u

DOWNSTREAM CHANNEL

VISUAL EXAMINATION OF	ON OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (OBSTRUCTIONS, DEBRIS, ETC.	EBRIS, ETC.)	Good. Some trees overhang channel immediately downstream of dam. Route 513 and Miggen Road bridges located about 800 and 900 feet downstream, respectively, of the dam.	13 50 5.f
SLOPES		Mostly wooded, stable. 20H:1V	
APPROXIMATE NO. OF HOMES AND POPULATION		One home in floodpath - estimated population of 2-4 people.	ation

CHECK LIST ENGINEERING DATA DESIGN, CONSTRUCTION, OPERATION

REMARKS	
R	None disclosed.
ITEM	PLAN OF DAM

CONSTRUCTION HISTORY None disclosed.

Prepared for this report.

REGIONAL VICINITY MAP

TYPICAL SECTIONS OF DAM None.

HYDROLOGIC/HYDRAULIC DATA None.

OUTLETS - PLAN None. - DETAILS None.

- DISCHARGE RATINGS None.

RAINFALL/RESERVOIR RECORDS None.

None.

- CONSTRAINTS

Commence of the Commence of th

ITEN	REMARKS
DESIGN REPORTS	None disclosed.
GEOLOGY REPORTS	None.
DESIGN COMPUTATIONS HYDROLOGY & HYDRAULICS DAM STABILITY	None.
SEEPAGE STUDIES MATERIALS INVESTIGATIONS BORING RECORDS	None.
LABORATORY FIELD POST-CONSTRUC'ION SURVEYS OF DAM	None.

Unknown.

BORROW SOURCES

ITEM	REMARKS
MONITORING SERVICES	None.
MODIFICATIONS	None.
HIGH POOL RECORDS	None.
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM DESCRIPTION REPORTS	None.

MA INTENANCE OPERATION RECORDS

None.

REMARKS	
ITEM	SPILLWAY PLAN

Prepared for this report from field inspection data. None. SECTIONS DETAILS

None. None. OPERATING EQUIPMENT PLANS & DETAILS

CHECK LIST HYDROLOGIC AND HYDRAULIC DATA ENGINEERING DATA

DRAINAGE .	AREA CHARACTERISTICS:_	5.3 sq. miles, partially wooded, hilly
ELEVATION	TOP NORMAL POOL (STOR	AGE CAPACITY): 635.0 NGVD (155 acre-feet)
ELEVATION	TOP FLOOD CONTROL POO	L (STORAGE CAPACITY): not applicable
ELEVATION	MAXIMUM DESIGN POOL:_	641.6 NGVD (half-PMF)
ELEVATION	TOP DAM:	637.1 NGVD
CREST: P	rincipal spillway - un	restricted flow over concrete
a.	Elevation	634.9 NGVD (upstream edge)
b.	Туре	concrete capped vertical
c.	Width	15'
đ.	Length	45'
e.	Location	right end
f.	Number and Type of Ga	tesnone
STOPLOG S	PILLWAY: restricted f	low (clogged with debris)
a.	Elevation	635.2 NGVD (top of debris)
b.	Type - wooden stoplo	gs - vertical; stoplogs no longer in place
c.	Width	20 feet
d.	Length	4 feet
e.	Location Spillover	center of dam
EMERGENCY	SPILIWAY	unrestricted flow over rocks
a.	Elevation	635.5 NGVD (low point)
b.	Type rock-lined bo	ttom, stone wall sides
c.	Width	varies
đ.	Length	20 feet
e.	Location Spillover	left end of dam
OUTLET WO	RKS:	4-foot long stoplog structure
a.	Туре	concrete vertical
b.	Location	center of embankment section

	c.	Entrance Inverts	635.2 NGVD	(top of	debris)	
	d.	Exit Inverts	628.4 NGVD			
	e.	Emergency Draindown	Facilities _		none	
HYDRON	ŒTEX	ORLOGICAL GAGES:	none			
	a.	Туре				
		Location				
	c.	Records		-		
		ON-DAMAGING DISCHARGE	483	3 cfs		

APPENDIX 2

PHOTOGRAPHS


LAKE AMES DAM




6 November 1979 Looking northwest at downstream face of prinicpal spillway.



6 November 1979 Looking east at downstream channel just below principal spillway.



6 November 1979 Looking west at upstream reservoir.



6 November 1979 Looking north across principal spillway crest. Note erosion on upstream face of north spillway abutment.



6 November 1979 Looking west at downstream face of stoplog spillway structure.




6 November 1979 Looking northwest across stoplog spillway structure. Note leak through main dam wall and cracking and spalling of concrete.



6 November 1979 Looking south across dam crest from north abutment. Note engineer standing on emergency spillway crest in foreground.



6 November 1979 Looking downstream through emergency spillway.



6 November 1979
Seepage at downstream toe of dam near north abutment.



6 November 1979
6 November 197 2-5 Ames Dam. LAKE AMES DAM



6 November 1979 Looking downstream from N.J. Route 513 bridge at second bridge encountered downstream of dam.




6 November 1979 Looking southeast at downstream channel just below second bridge downstream of dam.

LAKE AMES DAM

APPENDIX 3

HYDROLOGIC COMPUTATIONS

LAKE AMES DAM



REGIONAL VICINITY MAP

JANUARY 1980

DEPARTMENT OF THE ARMY PHILADELPHIA DISTRICT, CORPS OF ENGINEERS PHIL ADELPHIA, PENNSYLVANIA

ANDERSON-NICHOLS & CO., INC.

CONCORD,NH

MAP BASED ON U.S.G.S. 7.5 MINUTE QUADRANGLE SHEETS DOVER, NJ. 1954. REVISED 1970. AND BOONTON, N.J. 1954. REVISED 1970.

12

16

18 19

22 23

28 29 30

32 33

35

Subject LAKE AMES

Sheet No. of 16
Date 770 80
Computed 750
Checked 700

JOB NO. 3409-03

2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

HUDROLOGIC COMPUTATIONS

Dramage area = 5.3 mi2

Lake surface area (normal pool) = 14 acres

Evaluation criteria

size: small hazard: high

Spillway design flood
Based on size and hazard classification,
the spillway design flood will be
one half the probable maximum
flood (1/2 PMF).

Sheet No. 2 of 16
Date 250 F FO
Computed 100

JOB NO. 3409-03

DETERMINE TIME OF CONCENTRATION, To

Method 1*

Estimate velocity

overland flow reach largth = 1200 ft. slope = 990-955 = 0.03

from table; mostly "woodlands", average velocity = 1 fps

channel flow reach lungth = 11,300 ft. slope = 955-635 = 0.03 11,300from table, awage velocity = 1 fps

Tc = 1200 + 11,300 = 12,500 sec = 3.47 hz

Method 2

from nonlograph, $T_L = 1.25 \text{ hz}$.

TC = 1.67 TE = 1.67 (35) = 225 M.

*See Appendix 4, relevence 5.

Thee Appendix 4, 12 Prince 3.

JOB NO. 8409-03

Meihod 3* Overland form plope = 0.03 (see Netting 1) flow occurs mostly through woodlands; from plot of 90 slope vs. velocity, V= 0.45 fos Channel flow estimate channel shape 10 11 10 10 (10) $A = 10(1) = 10 \text{ ft}^2$ R = A = 10 = 0.83 ft. R = A = 10 = 0.83 ft. $V = 1.49 R^{2/3} 5^{1/2}$ 6=0.03, R=0.83, n=0.045 from Manning's nomegraph, V=4,8 fps $T_{c} = \frac{1200}{0.00} + \frac{11,300}{0.00} = \frac{1000}{0.00} = \frac{1.39 \, m}{0.00}$ 32 # fore Approximation 7.

JOB NO. 5409-03

35

Method 4*

Tc = 0.83(NL)0.461

for overland How

overland flow

N=0.60, 6=0.03, L=1200 14.

Trov = 0.83 (0.60 (1200) 0.467 = 40.6 min.

channel flow

hom Manning's nomograpio, V=4.8 fps (see Method 3)


TCCH = 11,300 = 2354 SEC = 39 min.


Tc = 40.6 + 39 = 79.6 min = 1.33 in

 $T_{CAVG} = \frac{1,33 + 1,39 + 2,25 + 3.47}{4}$

0.6Tc = 0.6 (2.11) = 1.27 k.z

* Sec Apoundix 4, refrance 7.





82. TO DIVISIONS FER INCH BOTH WATER OF ET DO CIVIDICAS.

Anderson-Nichols & Company, Inc.

Subject LAKE AMES

JOB NO. 3409-03

DEVELOP RATING CURVE AT LAN

Flow over principal spillway

Use weir equation, Q = CLH3/2

where $C = 2.6^*$ L = 2.4

Flow over stoplog spillway

Use were equation, Q = CLH3/2

where C = 2.8 * L = 4 #. H varies

Flow over emergency spillway and sam crest

Use were equation, Q = CLH 3/2

where C=2.5 L & H vary

tion, table ste, potrio, Brancha Cra, taraccoc of Augustice

Subject LAKE AMES

JOB NO. 7409-03

SCIARES 0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30


ELEVATION	SPILLWAUS						TOP OF DAM			
(FT. ABOVE	P21X	ICIPAL	EMERGENCY STOPLOG			HEAL	LENGTH	$Q^{ }$	Q	
NGVD)	HD(4)	Q(cfs)	HD (4)	a(45)	HD(4)	Q(6:5)	(#)	(#)	(c/s)	TOTAL
634.9										0
 635.2	0.3	19					i			. 19
636.2	1.3	173	0.7	15	1.0	12				200
 .637.1	2.2	382	1.6	72	1.9	29				483
637.4	2.5	462	1.9	98	2.2	37	0.3	92	36	633
 637.6	2.7	519	2.1	117	2.4	42	0.3	236	101	779
639.0	4.1	971	3.5	279	3.8	8 3	1.6	257	1288	2621
 640.0	5.1	1348	4.5	421	4.8	118	2.5	272	2731	4618
641.0	6.1	1763	5.5	582	5.8	156	3.5	287	4639	7140

[·] Head above lowest point on non-level crist.

30


^{*} Average value

PQ-CLH3/2 where C= 2.5



ONTERM OPPOSE THE TERM CODE BOOK CO NORWOLD WASH OPPOSE OF PERC.

NO. 31.292. 10 DIVISIONS PER INCH BOTH WAYS



இரைந்து In stock disect Prom Conex Book Co, Norwecob.

NO. SS.ZBZ. 10 DIVISIONS PER INCH


1

NO. 31,292. 10 DIVISIONS PER INCH BOTH WAYS

NO. 31,282.

() かんりかな in stock differ from code in non co. Horwood uses ca pen (

IO DIVISIONS PER INCH BOTH NO. 31.282.



CONTRACT IN STOCK DIRECT GR

TO DEVENORS PER INCH BOTH WAVE. 60 BY SO DIVISION

Anderson-Nichols & Company, Inc.

Subject LAKE AMES

JOB NO. 3409-03

32

35

SC ARES DUERTOPPING POTENTIAL 11 12 40

10

SPILLWAY CAPACITY = 483 CFS 2000 10000 DIACHARGE IN CFS

HEC-1 OUTPUT

OVERTOPPING ANALYSIS

LAKE AMES DAM

	A1LAKE TE	ALLAKE TELEMARK-LAKE	AME		AM OVERTO	PPING A	NALYSES BE GOSHA	SH GONHARRY	RRY A-MECO	## CU			:		
: 	A	HULTIPLE	PMF 10	FROM 24-H	-HOUR PMP	- CRFA	FREACH ARALYSI		OF RUCKA			:	:		
r. u ~		6. 25. 25.	- 5.0	:	:	:	. .			•	: !			. :	
a. c ç	KI DEVELC	A1 OP LAKE 1	EMARK 1	NFLOW	HYDROGRAPH	- SUB-ARE	REA 1		-						
>	S	72.7		123	132		-	0.1	•	:		i .	:		
. * R 7	K 1 ROUTE	,	A 2 INFLOW HYDROGRAPH	THROUGH	LAKE	1 TELEMARK	-								
	1 5 5		673.2 239	674		675.0 2592	70 675.5 3662 130	-1 676.0 48ē5 160	677.0 7778	÷ .	i i i	:			
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	944	•	i .	671.	572.0 570.0 570.0	673.2 673.2 685.0	1	677.0						·	
& & & & (\(\(\nu\)\) \(\nu\) \(\n	X1 CHANNEL Y1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	FL ROUTING 1 0.05 674 566	0 · 05 32 116	663 670 670	674 64 148	50	0.012	£99	· «	663			:		
THE WEST	CH7		-H00 0 0 0 1		ELEHARK ROAD 1 1 1 2 672	` .	0.012	299	6	662				•	
	CHAN	ROUTER		1 00	~	2390	1-10-012		! ! !			; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;			
~~e~c	172 172 172 1	AST LAFF	PO PIES INFLOW	E S	1 255 1 255 1 257	66.4 6.5 7.5 8.7 8.7 8.7 8.7 8.7 8.7 8.7 8.7 8.7 8.7	160	635	172	F35	:	:	1		

PREVIEW OF SECUENCE OF STREAM NETWORK CALCULATIONS

A 1	₹	K. 4	6	ر 4	Ας	A 7	8	8 9	A 1 0	A 1 1	A12	F. 1 V	:
RUNDEF HYDROGRAPH AT	POUTE HYPROGRAFH TO	POUTF HYPAPERAFH TO	ROUTE HYDROGRAPH 10	POUTE HYDROGRAPH TO	RUN OFF HYDROGRAFH AT	DFEIN	HYDROGRAPH		OUTF HYDROGRAPH	APH	ROUTE HYDROGRAPH TO	NUTE HYDROGRAPH	

0.016 100

100 218

567

ره ت 0 LAKE TELEMARK-LAKE AMES TANDEM DAM OVERTOPPING ANALYSES HU G-SHARRY A-NACO UM New Jersly day Nos-22-29827-27 Afspctvly Worris County-Tounship of Rochanay 0-5 multiple of PMF FROM 24-Hour PMP — Breach Analysis NSTAN ALSMX ISAME P 96 0.00 653. 2°2. 60. IPRI HOURS, LAGE CNSTL .10 NONSI R72 572. 347. 76. STRTL MULTI-PLAN ANALYSES TO BE PERFORMED NPLAN 2 NRTIG= 3 LRTIG= 1 PAT10 R48 JOB SPECIFICATION

IRR THIN METRC

0 0 0 0

NUT LROPT TRACE METRC 0 TRACE SUE-AREA RUNOFF COMPUTATION 196 TELEMARK INFLOW HYDROGRAPH - SUB-AREA 458. 421. 92. UNIT HYDROGRAFH DATA HYDROGRAPH DATA
THSDA TRSPC PRECIP DATA P12 n24 123.00 132.00 RECESSION DATA ITAPE 0PD1HATES. 326. 502. 96. STRKS ORCSW= 1ECON ERAIN 0.00 FEB10D 216. 56.9. 117. SNAP PHS | FK JOPEP 5 6 1.00 6 1AREA 2.50 STRIGE SP FND NH IN DLTKR 0.00 PYCRUCRAPH 5PFE 0.00 DEVELOF LAKE DAM SAFETY VERSION - JILY 1978 LAST MODIFICATION 26 FEB 79 00.0 70. £71. 177. 31. STRWR 201 1 dua 1 DATE: 19/12/31. TIME: 08.18.20. 701. 107.

Ç

(

ŧ

 \mathbf{C}

	-02				P74.70)
					2 - 69 - 2 68 - 3 (
		000000			21.29
	9999				23.97 (609.) UNE 331. 74. .57. 24.
20 E	160 161 162 163	167 167 167 170 170	171 172 175 176 176 177 177 181 181	1856 1866 1866 1867 197 197 197 197 197 197 197	50P
(C)	4 W D = W	ಬಟಟಕ ದವರ 	4 4 4 M M M M M M M M M M M M M M M M M	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	HOUF T 037. 29. 1.99. 1.99. 19.57
					2008 2008 2008 2008 2008 2008 2008 2008
-	S - K C: C:	50 できょう 200	こころちゃりららめらばくりだ…ろうこう ちゅうきょう ちゅうきょう かんごう かいてん かいごう	10 00 00 00 00 00 00 00 00 00 00 00 00 0	24-H0 143 143 1 543 1 243 351
20.00	~~~~	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0 0 0 0 0	20 20 20 20 20 20 20 20 20 20 20 20 20 2	6-H0UP 1830 18 00 2349 2349
00	C D C C C		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		7839 - 222 - 222 -
 	606651		D D 4 4 4 4 5 5 5 5 5 5 6 6 6 6 6 6 6 6 6 6		CFS CHS INCHES AC FT
£ €.	*******	5 4 4 4 4 5 F F	ファイファファフルのようで	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	THOUS
. 4				0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	!
2.5		6000000			

160.

130.

100

22

. 23 20

70.

CAFACTIY=

								•	•			•	
		•		•	•	•	•	•	•		•	•	
:	•	•	•	• •			•	•	•		•	•	
	•	: .	•		•	•	•	•	•			•	
	•	•	•	•	•	•	•		•		•	• `	
			: 		•			12.		!		3130	,
			1 4	2 4					* 0 U				
	* * * * * * * * * * * * * * * * * * *		•	10 6	•	0.00		- 1				• • • •	
	167	163	105			-	623			٠		. tb .	
	000	***			•	•	. 170	16.76	1070			• •	
	1 2 2 2 5			7 - 1		•		- CO-C	1455				
:	27.10	25.56	5476	516		000	I ROS	1606	1825	1945			
	- 10 17 - 3 1 B	806.	4.60	764			0 4 5 c	688	0.45				
	2.50	204.	181	163		147.	133	121.	111.				
	87.	B1.	-	71	; 	æ	65.		60.			53.	
	66		40.	Ř	36.	31.	28.	24.	21.	-		16.	
	1.	13.	11.	1	0.	9.	æ	æ	7.		7.	÷	ł
		.0	•		ı.	5.	un •	ır.	•		•	•	
	•	÷	÷	~	•		:	•	•		•	•	
	•	•	٠	-	•	•		•		!		•	
				A 7 3 0	911011-3	Ottob - Ac	91011-01	IATOT 91	100				
		Ü	* 7	75 m.	2419	r	~	-					
	*	5		111.	F. A.	20.			2937	1	!		;
		INCH	so:			_		72	10.72				
		(1) (4)	¥.		228.60	271.79	2	53	272.29	: : :		:	
		AC-FT THOUS CU M			1199.	1426.	1429.	• •	1429.				
	•											1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	:
45 C H 4 H	NA IO NA BIANT												
	· · · · · · · · · · · · · · · · · · ·		:	-									
	• • • • • • • • • • • • • • • • • • • •	:	•	:	•	••••••			•	•	*****		
					HYDRO	HYDROGRAPH ROUTING	1180						
	108	ROUTE INFLOW	HYNPOGR	HOW HYDROGRAPH THPOWER	NÜĞH LAKE	E TELEHARK	٠			•	•	1	
							•						
			TSTAG	IC ONP	IECON	ITAPE	JPL 1	JPRT	INAME	ISTAGE	IAUTO	1	
			i L	•		•		•	•	•	>		
					ALL PL	PLANS HAVE	SAPE			:	•		
		0L055	CLASS	AVG	Ξ	SAME	9	IPMP		LSTR			
i		•	0.00	00.0	-	-:	6 .	0		c ·			
			PISTPS	NS TOL	0 T T	AMSKK 0.000	× 0 . 0 . 0	15K 0.000	STORB 70.	ISFRAT-1			
37873	66.7.00	471.10		673.2"	674.0	E	674.46	675.00		675.50	476.00	677.00	00.
אל טונ	00.0	21.00		239.00	00.706		1682.00	25,9200		3662.ñ0	48PE . 00	7777.00	=

677.			
	EXPL		
675.	CAREA 0.0	:	FAILEL 673.20
	CAR	VIO.	USEL 670.00
673.	0.0	DAM	0.49
	0	ATA EYFD 0.0	DATA TFAIL 1.00
£72.	FLEV 0.	COOD EYED DAMUID	REACH BM BM
	7 A A	S	DAM BREACH DATA ELEM TFAIL G.OC 664.RA 1.00
671.		TOPEL 673.2	0.00
	0.0		ē.
£70.	SPUTD COOV EXPW FLEVL COOL		88410 17•
	i		
.643	CREL 669.0	i	
	-	: :	
665.	!	:	
		i	
101=			
ELEVAT	1	;	
w			
		1	

PEGIN DAM FAILURE AT 13.50 HOURS

STATION AS PLAN 1. RATIO 3

FND-OF-PERIOD PYDROGRAPH OPPINATES

		•				. ~			3 6	2 :	5	ت 1	1362.	6	Œ	4	. 0.	25.	•		۲.		69.	.69	68.	67.	. 66	79.	91.	_	5	124.	25	2	^	42.	m	œ	24.	25.	21.	. 21.		E.		C.	₽.	•	_	671.9
	9.		-	, ,			. 6	200		- 1	- ·	2	1455.	535	0.3	8.	S C	27.	15.	10.	.		69	69		67.	67.	17.	-06	02	9	122.	8	0	65.	6. 47.	34.	2 R •	24.	22•	21.	21.						669.7		671.9
	c [*]	€.	.	7.			٠.	, r			و ع		15.04.	96	\sim	0	57.	œ	ď	10.			. •69	c	Œ	67.	_	•	90.	9	5	120.	25	07	•	• •	4	29.		n,	21.	21.				•		F 6 10 - 7	•	6.71.9
		9.			7.	. 4		. «		ń.		613	775	_	N	113.	61.	. 30.		10.	۲.		69	69	=	æ	67.	4	6	9	9	~	20	60	ς.	ا اور	ır.	56.	25.	23.	21.	21.		6.69.9	6.6 19	660.0	669.8	(60.7	6.70.4	1711.7
5 4	10.	•	ai			-	. 62	165,		1550	-	3752.	1000	729.	265.	120.		33.	15.		æ	:		9	68.	6.8°	67.	73.	88.	95.0	108.	114.	27	112.	76.	48.	36.	30.	: 25.	23.	22.	21.		ċ		•	5	669.7	•	671.6
	10.	σ,	æ					146		Š.,	3	857	5	801.	251.	~ 1	70.	٠.	19.	11.	œ	STORAG		6	læ	5.8.	-	72.	4	C	6	112.	27	4	Ö	50.	ď.	0	56.	23.	22.	21.	STAGE	0.0	•	•		6	•	6.11.5
	10.	٠.	· 6:	. c	7.		504	140.	3 6	- 20 OT	ا ي د د د د	710	2317.	893.	320.	138.	74.	37.	20.	12.	œ		70.	6.9	6.0	~	67.		ut:	C.	-	0	28	_	•	5.5	~	31.	26.	•	22.	_		6.07.9	6.699	F. F. P. P.	и•699	6.69.7	6.70.0	6.71.4
	10.	9.	æ			٠.		3 0		2 19 2 19 2 19		0	247P.	600	دنا	~	19.	•0•	21.	-2-	•		70.		ia	ς.	£7.	_	84.	Ç,	_	6	3	_	Œ	54.	CC.	_	56.	23.	25.	21•		470.0	6.69.9	660,8	6.69.8	465.7	470.0	671.2
	10.	9.						- 0	• • • • • • • • • • • • • • • • • • • •	ø,	-	æ	2659	-	390.	160.	•	•		13.		:	70.		6Я•	Œ		6.9	A2.			108.			93.	و ان ان	39.	32.	27.	24.	22.	21.								671.1
	10.	9.		ά.		- 6	• •			•	· ·	Œ.	2845.	•		173.	۳. ۳.	4 F.	2.3	14.	¢.		10.		Ċ		5.7.	f.B.	p () •	92.	03	107.	ž	120.	97.	50	40.	32.	27.	- b -	22	21.			-			1.693		£77°
																																									•									
<u>-</u>	i	•	_				-	_			<u>.</u>	<u>-</u>			ş	.	-	-	•		_		Ţ	-	· ·	<u> </u>				F		Ţ		Ē	-=	<u>:</u>	-	•		ž.	•	1	<u> </u>			_;	_7			-4-

3910. AT THE PEAR OUTFLOW 15

CFS CFS INCHES PH AC-FT THOUS CU N

 \mathbf{C}

C

0

. . .

0 6 E

0, C, K

. . .

STATION A2, FLAN 2, RATIO 3 EKÖ-DF-PFFICH HYDROGRAPH ORDINATES

10. 10. 10.

10.

...

										. []	Æ		==.	Į E.E	<u></u>		•	`. <u>.</u>		-		? :	<u></u>	1-7	-	` '	•	<u>^</u>	: :	-	\ }';	(, -	()		C	· 		<u></u>	<u> </u>	(Σ.	_	ر سی وسی فد هد	Ξ.	([]		<u> </u>	_ ල		
																			•										•					1.																	
		٠						•										,							•				:										,												
7.		.8.				0 11				4	47.	21.	19.	17.	16.		49.	69	6 P •	67.	.89	79.	91.	100	122.	1000	119.	107.	98	911.	82	P.O.	78.	76.		6.69.9	6.64.9	-		_		671	_	6/4.4		_	6.73.3	6.12.5	671.5	671.4	(- 1.1 · 1
.	7.	$\stackrel{\sim}{=}$	100	2 4			7 0	0 G	· œ	2	3 5	-	19.	17.	16.	·	6.69	69.	. 83	67.	67.	17.	•06		22	1 35.		108.	•66	91.	8 28	80.	76.	76.		6.699	ċ.		469.7	ď.	<u>.</u>	ᆣ,	٠.	674.5				•		671.0	
÷,		- 12°	. 26			• • • • • • • • • • • • • • • • • • •			190	100	95	23.	19.	18.	16.		69.	69	6.P.	67.	(,7.	76.	90.	90	120.	136.	122.	108.	100.	9.1.6	82.	80.	78°	76.		•	•	•		•	•	•	•	674.3			-	•	-	6.71.4	
. ,	۲.	14.			77	46.45	7 7 6	- M	199	114	09	25.	-02	18.	16.		64	69.	68.	, R	67.	74.	F.9.	97.	1 19		124	60	102.	924	82	.0A	7A.	77.		6.699	6.633	8.69.8	669.8	669.7	670.4	6.71.7	- C	678.9	6.75.5	674.5	473.4	672.A	0.27.0	2.167	
٠,	۲.	13.				+ 0 4 C F	1967	5	209			28.	20.	æ.	16.	الما	,	• 69	68.	68.	67.	73.	8.	95.	128	- en-	125.	110.	103	0 P	. ec	81.	62	77.		70.	٥	69.	9	69	20.			F 74 . 1	7	79.	673.5		672.1	6.71.5	
œ. ı	۲.		, F.I.	104	٠,	.0.00	. c		218.	128	70.	0	20.	- B-	16.	STORAG		6	6A.	Œ.	61.	72.	(2)	-	117.	139	126.	112.	104		. m		79.	77.	STAGE	2.006	6.695	8.69	H. 99	569.7	1.07	0.0		7.4.0	72.6	74.7	573.6	673.0	77.1	7. 1. v. (

72 72 72 73 74 74 74 74 74 74 74 74 74

アルス ルムごろ の ちょう ちょう はっぱん カイア ひき ちょう ちゅう ちょう ちょう ちょう ちょう ちょう カイト

5570.00 66559.99 66599.99 66799.99 67799.90 67799.90 67799.90 6779.90 6779.90 6779.90 6779.90 6779.90

6470°00 6476 647

6670.00 6689.90 6689.90 6689.70 6672.00 6673.00 6773.0

6470.00 66670.00 66670.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00 66770.00

				,							:	.16	994.09	66P.21 674.00	60.4.6
	# !			*	!			;		:		.13	765.76 6154.49	667.63	765,476
	:	•		1	1AUTO .		;		:			.10	583.40 5239.00	667.05 672.84	24.50
	: :			i !	1STAGE		LSTR	ISPRAT	:			.08 .57	58.94 :0.91	.6.47 72.25	4
L_VOLUME 103270- 2924-	271-12 1422 1755	• : •		•	INAME 1	1		STORA -1.			:		4 4		
				:	JPR1	:	1040	15K 0.000			84.00	.07	324.02 3695.36	665.R9 671.68	
72-H9UR 516- 15-	271-12 1422 1755		JNC		JPL T	ME	1961	0.00.0			663.00	.05 .43	1.34	1.32	,
24-HOUR 714. 20.	269.90 1416. 1747.		APH P.OUT		ITAPE	SHAVES	ING DATA ISAME 1	AMSKK 0.000		SEL 1200	64 • 00		305	6.67	ļ
i	28.44 1199. 1478.		HYDPOGR	ACH 1	1ECON D	ا ن ۔	RES 1	LAG		PLNTH 50.	646.00 674.00	.04 3f	147.25	664.74 679.53	
EAK 10. 11.	2			PULS- RE	1C 0MP		00.0	NS TOL		ELMAX 674.0	LEV+STA+ 64.00	.03	P- PC	40.00	
				00H- 9	ISTAG		0.00.0 0.000	NSTPS 1			670.00 670.00	,	202	99	1
	AC-F1						0+0			AN(3)	008DIWATES 0 32.00 0 116.00	.01	25.29 1616.59	663.5A	
		•		CHĀNI	•					08(2) •0800	SECTION CO 12 674.00	0.00	0.00	56.3.00 56.8.79	,
		. •		:					DEPTH CHI	00113 •0580	68088 0.48	٧ د ن	OUTFLOW 12	STAGE	
	CFS 3910. 2417. 714. 516. CMS 111. 68. 20. 15.	CFS 5910. 29+10UR 72-H0UR TOTAL V CMS 111. 68. 714. 516. 10. NCHES 113. 68. 70. 15. NCHES 10.63 10.67 AC-FT 1199. 1416. 1422. CU M 1478. 1747. 1755.	CFS 3910, 2917, 714, 516, CFS 3910, 2917, 714, 516, CMS 111, 68, 10,67 15, CMS 111, 899 10,63 10,67 10,67 10,67 10,67 10,67 10,67 11,99, 11,416, 14,22, 17,55, CU M 14,78, 17,47, 17,55,	CFS 3910. 29-HOUR 72-HOUR TOTAL VOLUME CFS 310. 2917. 714. 516. 103270. CMS 111. 68. 20. 15. 2724. INCHES 10.67 10.67 10.67 10.67 AC-FT 1199. 1416. 1422. 1755. THOUS CU M 1978. 1747. 1755. 1755.	CHANNEL ROUTINGHOD PULS REACH 1	CFS 3910. 24-HOUR 72-HOUR TOTAL VOLUHE CMS 111. 68. 20. 516. 10.57 INCHES 8.99 10.65 10.67 MM 228.44 26.9.60 271.12 271.12 AC-FT 1199. 1416. 1422. 1422. THOUS CU M 1478. 1747. 1755. 1755. HYDPOGRAPH POUTING CHÄNNEL ROUTING -HOD PULS- REACH 1 ISTAG 1COMP 1ECON 17APE UPLT UFRT INAME 1STAGE 1AUTO P. 1	CFS 5910. 29+PUR 72-HOUR TOTAL VOLUHE CFS 5910. 29+PUR 72-HOUR TOTAL VOLUHE CFS 111. 68. 714. 516. 103270. CFS 111. 68. 714. 516. 103270. AC-FT 1199. 1046. 1422. 1722. THOUS CU M 1478. 1747. 1755. 1755. HYDPOGRAPH POUTING CHĀNNĒL RDŪTĪNG -HOD PULS- REĀCH 1 AS 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CFS 3910. 29-HOUR 72-HOUR TOTAL VOLUME CFS 3910. 714. 516. 10.57 CMS 111. 6.63. 10.67 INCHES 111. 6.89 10.67 AC-FT 1199. 1416. 1422. 14476. 1747. 1755. 1756. 1747. 1747. 1755. 1756. 14070. 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	CES 3910. 24-HOUP 24-HOUR T2-HOUR TOTAL VOLUME CES 311. 516. 20. 20.270. CHS 311. 6.9 71. 516. 10.67. INCHES 111. 8.99 10.63. 10.67. HH	CFS 3910, 7917, 714, 516, 1020P CFS 3110, 714, 516, 105210. CHANNEL ROUTING O.0 0.000 0.00 0.00 0.000 0.000 0.000 0.000 0.000 0.000 CFS 3110, 714, 516, 10570. CFS 3110, 714, 516, 10571. CFS 3110, 714, 516, 10571. CFS 3110, 714, 516, 10671. CFS 3110, 714, 516, 10671. CFS 3110, 714, 516, 1067. CFS 3110, 714, 516, 1067. CFS 3110, 714, 516, 1067. CFS 3110, 714, 714, 1067. CFS 3110, 714, 714, 1067. CFS 3110, 714, 714, 116, 1167. CFS 154, 714, 715, 715, 716, 1067. CFS 16, 706, 714, 116, 1167. CFS 16, 706, 714, 1167. CFS 16, 716, 716, 716, 716, 716. CFS 16, 706, 716, 716, 716, 716, 716. CFS 176, 716, 716, 716, 716, 716. CFS 16, 706, 716, 716, 716, 716. CFS 16, 716, 716. CFS 16, 716, 716. CFS 16, 716	CHINNEL ROUTING CHANNEL ROUTING CHANGE ROUTING CHANNEL		CHANNEL ROUTING CHANNE	THOUS CO The The	CHANNEL ROUTING CHANNE

0.00 K L L 20.00 K 20. 9. 8. 7. 15. 175. 276. AS. PLAN 1, RTIO 3 10. 10. 8. 8. 8. 7. 11. 11. 126. 116. STATION 10. 10. 10. 10. 10. 10. 10. 10. 10.

Yannin Jan

13.00	# 1	2566 2591 2750 3750 3750 3750 3750 3750 3750 3750 3	252. 113. 102. 103. 103. 103. 103. 103. 103. 103. 103		00 00 00 00 00 00 00 00 00 00 00 00 00	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		00000000000000000000000000000000000000	40 K P K O	∝ 5 ∙ 6 ∩ ∼ .	
	10000000000000000000000000000000000000	25			087507 0000000000	\$ 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
	2 7 7 5 7 7 5 7 7 5 7 7 5 7 7 5 7 7 5 7 7 5 7 7 5 7 7 5 7	2 N H H H H H H H H H H H H H H H H H H		18201 18201 190000000000000000000000000000000000	00000000000000000000000000000000000000	25.50 25.50 7.00	
	17.0.1 0.0000000000000000000000000000000	800000000			10. 10. 7. 7. 7. 7. 9. 9. 9. 9.	7 - 7 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
		# NO DO				7 . 0	
	12. 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	**************************************				7.	
	® 000000000000000000000000000000000000	# CO				• 00	:
		**************************************				•	
		X					
						• •	
						•	
						•	
							,
		000					
						•	
		000					
		00-					
		•		00000		• 0	
		-				•	
			0.00				
		•					
. 0				.	•	•0	
0.		•		c			
				• >	ئے	•0	
		0		•			:
		. •			•		
			0	.			
		0.0	•				:
				: -			
	•	,	•	}		•	
		STAGE	1				1
199 6127 6	63.2		4	6,532	663.2	641.2	
2000 30000 31 2000 30000 31	2.5		66.4.9	21.00	2.000	2000	
2000 20000 0				2000	2000	000	
***** C # **	7.5	u c		000	200	0 FO	
**************************************	7 6	ų c		0000	000	7.694	
5653. 5653. 5653. 5653.	200	7		20000	2000	665	
5 563.2 663.	2004	3		663.0	663.	0000	
.4 663.5 663.	63.8		.	669.3	664.3	C F B . B	
5 664.5 664.	F	9	.	6. 499	665.1	665+3	
.4 667.3 667.	68.3	9	æ	669.	469.1	669.1	
.2 (67.4 k69.	69.7	6.	•	6.70 . R	671.1	671.4	
.7 K71.8 K71.	71.9	æ	æ	671.5	671.3	671.1	
.9 k10.7 670.	70.3			669.3	669.1	66.9	
.7 668.5 668.	68.0		ٺ	667.1	6.9999	9•999	
.4 (.66.2 666.	F5.9	- 1		665.3	665.1	665.0	
. KA.B KA.	64.7	پ		664.4	664.3	664.3	
.3 564.2 664.	64.1	-		663.9	663.9	663.R	
, A F. F. F. S. B F. F. F. S.	٠,	~		663.6	663.E	663.6	
£ 7 655.5 655.	1100			6.5.3.	663.3	663•3	
.3 663.3 663.	63.3	•		(6.7.2	663.2	663.02	
663.2 663.	F3.2		663.2	663.2	663.2	663.2	
10	AK 4-110U	24-F0UR 72	-HOUR TOTAL	VOLU**			
		ر. 10	• W	2000			
:	•		•				
/ 1/12 C	>			-			

AS+ FLAN 2+ PTIC 3 STATION

.01

<u>.</u>

۳.

<u>.</u>

NUTFLOV 10.

16.

1478. 1823.

1478.

1472. 1815.

1212.

AC-FT THOUS CU N

MAXIMUM STORAGE =

6.11.9

HANTHUP STAGE IS

¢.

ġ.

·

-		,		-					-						: [- y-			:						<u>*</u>	`* <u>-</u> :		7.1 3.	***		Ē					1	2 . آ⊾	-5.4	:		- 				-		
• «			18.	~ 1	N 4	-		0	8	~	96.	97.	21.	•	16.			•	• •	• 0	• •	•0	•0	•		• •			• 6	• 0	•	• 0	• •			663.2	•			•	•	•			•	•	664.3
o. a	: -	7.	16.	66	~ •	-	• •	2	4.9	100.	102.	51.	21.	· ·	16.			•	• •						5			•			•	•	•	:	663.2	663.2	663.2	663.2	663.4	664.3	665.1	569.0	671.3	66R.9	666.0	C. 53.7	664.4
E . «			100	6 1	200	782	6.7) M	400	6	Ö	56.	23.		16.			• . • •	• •		•	•	•0	•	•		•	ô	• •		•	•	• •		663.2	£63.2	663.2	563.2	663.3	664.3	6.499	668.9	671.5	669.2	FF6.3	665.0	664.4
o	i a	7.	14.	•	~ °	. 5	1	1711.	459	199	114.	•09	5 20 0	• ·	16.			• •	• •	•0		•	0		0			•	•		0				,,	663.2	,, ,	;;		•	•	• •	• -	. 6	÷	665.1	
e e		7.	13.	~ .	==			6	530	0	5	ĸ.	S. S.	•	16.			•	• •					•			0		• •				• • • •		€3•	663.2	ğ.	9 6	9	64.	• • •	9 6	: :	6.9	66.	65	
• •	ec			3	136.	18.7	ا د کا لا کا د	. 0	3	218	C	70.	900	20.	16.	,	STOR	• . • c					0	• •	0	•	0	.	• •	•	• 0	0	• •	CT ARE	63.2	663.2	5	9	63	64.	9 9			70.	67.	ه. د دی	•
5 &		7.	0		900) - \ 0		706		9	40.1	33.	Ď 8	17:			•	• é			:	•	•		• -	0	•	• • • •		0	•0	• •			663.2				Š	•		•	. ~	:		•
e «	• • • •	7.	10.	S		: =		35	R 0.9	, 177	:	0	9 (0	17.			•				;	•	•	•	• •	c	•	• •	0	• 0		• • • •	- 4	'n	663.2	÷.				- 1	: .	: :		:	ŝ.	:
• a		7.	9.	2	7 1 4	- 6		5 5	100	3.9	53	9	04	0	17.			• •		0		•	0	•			0	•	• 6			•	• •		*	663.2	÷.				٠,	: :	: :	: :		ů.	:
.		1		<u> </u>		2		5	-	268.	<u>-</u>	6	* PO *	21.	17.		*****	•				_	0	0	• e	• •		•	• ¢		•	.	• •	i		663.2	•			-		•					•
		•										!			:					:												1												,			
			<u>~.</u>	1	=-;					i				_	-	_		_	.	:		-3			:							į							; I		İ			;		i	

Care C. L. As No. Co.

	. <u> </u>	Julion.	. ALLOTETET		FIFE	1	<u>lterter</u>		usen.		6 6 EXERT)	
:				i			:					 	543-78	
	:									:	:	• • • • • • • • • • • • • • • • • • •	450.20 4267.26	
663.4 663.4 663.4				•	1	AUTO					; ;	. na . 1 x	378.72	
663°4 663°4 663°4	;			• • • •		ISTAGE I	LSTR	ISPRAT			:	.03	302-95 335-00	
663.4 663.4 663.4	آ	1755		• • • • • • • • • • • • • • • • • • • •		INAME 1		STORA -1.		:	0u 662•00	•03	(V)	
663.4 663.4 663.4		1755	•1	***		T JPRT	O O	TSK 00 0.000			662.00 94.00	• •	231.6	
663°B 663°B 653°B	72	1797			YDROGRAPII ROUTTNG Mark Road BP10GE	JTAPE JPL	TAVE SAME DATA SAME TOP	15KK 000 0 0 00		פו	PD • UQ 652	0.0	165.79 1277.09	
663.4 663.4 663.4	6-HOUR 24- 2417- 68- 8-99 1		JH STORAGE	4 4 4 4 4 4 4	HYDROGRAPH TELEMARK ROAD	IECON 11	ALL PLANS HAVE S ROUTING DATA IRES ISAM	LAG AM		30 • 01200	LEVETC 668.00 672.00	20.	106.80 993.25	
663.5 663.4 663.4	FEAK 6-3911. 2		MAXINUM		PULS-	ICOMP 1	i 1	NSTOL		572 • 0	ELEV.STA.ELE	.01	56.68 820.40	
563.5 663.0 663.0	CFS CHS INCHES	CO H		***	ROUTING -POD	ISTAG	000 • 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	WSTPS 1	:	149	47ESSTA-ELEV -00 670-00 -00 670-00 1	. 0 . . 0 .		
663.4 663.4 663.4	Z	THOUS CU	671.9		CHANNEL RO		orus.	;	ROUTING	00 00160	ISS SECTION COOPDINATES 0.00 6.72.00 94.00 114.00		18.6F	
8.83.8 6.83.8 6.83.8		i i	12 13						H CHANNEL	.0169 .0462)	CHOSS SECTION OF OR STATEMENT OF THE STA	មិន មិន មិន	624.02	
; !		:	MAXINUM STAGE						NORMAL DEPT	0.	.	STORACE	OUTFLOW	

€ 0 304000 98677 **** 26 g a r 4 A4. PLAN 1. RTIO 3 13. 12. 10. 10. 8. 8. 7. STATION 5 - 8 - 6 2 - 8 H - 5 94.6 00000 <u> TERRETT</u>

540.78 5635.14 672.110 458.20 4267.26 671.47 670.05 378.72 670.42 302.95 68.643 231.64 1277.09 669.37 104.80 668.84 50.68 820.40 668.32 467.79 18.68 92.199 0.00 FLOU

7-


:																:					1					:				:					i			•								
231	Ø !	9	90	L C.	95	50.	25.	14.	6	7.	•	.6	ô	0						.										•	•	•	•						•					•	•	f 62 • 3
199	زنع	243		4	20	'n	~	15.	0		:	0	•	0		•			•	0	•	• c				•		•		٠	å	٠.			-		•	<u>.</u>	• •	•	•	:	'n	ċ	å	662.3
175. 1496.	2764.	4 t		222	106.	57.	28.	16.	10.	7.			•		• •	• •					•					•				\sim	~ ∙	\sim $^{\circ}$	\sim	. ~	2	•	or o	• •	- C	· •		_ №≎	M	~	•	662.3
15.7	· .	F.14	= :	2 5	2	61.	30.	17.	—	7.		•	•	•	• •	•	•			• 0		• •	•	0	•			•0		ů.	ċ		• 6		663.3		6		• •		9				ċ	662.3
145 329	8	75.4		266.	120.	F.S	33.	8.	11.	*		•	0	·	<u>.</u>	•				0		• •								62.	62	÷ (20	29	63	63	9	0.5		7,7	4	5.3	63.	۲. 2°	5.2	662.3
136.	- 1	7 1	ي . ب	<u>-</u> د	نه،	0.2	÷ún Ko	19.	11.	å	STOR	•	•	٠,	ů		• •	•	•0	0	ò	• 6							STAGE																	662.3
130.	1867.	911	519	321.	ريد ه رسم و	15	37.	50°	12.	ċ		.			• •	5 6	• =		• 0	•			•				•			٠,	å	ů.	• •		6.299		ė.	<u>.</u>	• .					•	•	6.6.2.3
124	v.	506			146	79.	- 6	21.	12.	œ.	•	0	•	0	.				0		0			•		210		•																		667.4
119.	1660.	3	26.61.	3 =	160	84.	4.3.	22 •	13.	*		•0 .	•		.	• •		•	.0	0	• •									\sim	សំ	ດີເ	• 6		F62.5	÷	٠.	• •	• .					•	•	
113.	1536.		7.4	- i	173.	0.0	. 6	24.	14.	e ar			•	•	• •	.		ت د		•	.			0	.	•					٠.	٠,	• .				٠.	•	• -			:	•			64.2.4

72-HOUR TOTAL VOLUME 24-HOHE C-HOUP FF AK

CFF 3911. 2444. 742. 537. 107352. CFF 111. 64. 21. 15. 503R. INCHES 9.09 11.09 11.09 11.09 RC-FT 1212. 1472. 1478. 1478. 1495. 1815. 1823. 1823.		•						
111.	S-10		2444.	745.	537.	107302.		
9.07 11.09 230.94 280.52 281.70 1212. 1972. 1978. 1995. 1815. 1823. HAXIHUH STORAGE = 0.	5.13		• 6 7		• 64 • 64 • 7	- 20° - 0° - 0° - 0° - 0° - 0° - 0° - 0°		
210.94 240.52 281.70 1212. 1472. 1474. 1495. 1815. 1823. HAXIHUH STORAGE ≅ 0.	274741		9.09	11.04	11.69	6.D • I I	,	
1212. 1472. 1478. 1495. 1815. 1823. HAXIHUH STORAGE = 0.	. I	:	210.94	280.52	261.70	281.70		
1475. 1815. 1823. HAXIHUH STORAGE = 0.	T I I V		1212.	1972.	1478.	1478.		
HAXTHUH STORAGE = 0.	H DO SHOHI			1815.	1823.	1823.		
HANTHUM STORAGE = 0.								
			AXIMUM STOR	AGE =	. 0			

404

PAKTRUM STAGE 15



1			STATION	A44 PL	AN 2. RTI	ю о						
			-									<u> </u>
	5 6	> C.	-	5	• 6	. 6		. 6	e e			
	60.	•	80	e.	8			æ	«	•		
	÷ ~	¢ ~		e .		æ ~			. 8			<u></u> -
		10	. =		· 0	14.	10	16.	~			
	2 5	8	4	61.	~ -	P2.	5 1	466	107.			<u>. T</u>
	587	718	2 4 8	000	113	1224	28 :	422	3 5			<u>::</u>
	1690.	1787.		056	ف	2492	-	3101.	-			. [
	829	903	911	26	5	615	200	251	039			7
	910	7000	706	19	Siv Siv	460.	2.6	اران 10 ماران	30	:		
	39	233	N	-	0	199.	90	2	~	,		
i	60		₩,	CV!	N	114.	8	2	Ç.,			Z
	٠	0	~	10.	65.	•09	9	51.	•			<u>.</u>
	0	4	2	- (∞ •	26.	m (21.	21.			
•	010	Die	ole	o!e	20.0	20.	17.	19.	14.	:	:	<u> </u>
		17.	17.	16.	. 9 19 19	16.	16.	16.	16.			-7:
i			. ;			; ; ;) ;			:		_:.
		•	•	STOR		•	. •	•	•			7
	• •	• ,	• •	• 6	• (• •	• •	•	• •			17
			0	0		0					:	<u>:</u>
		•	6					•	0			Ξ
:		. 0	0.	•		•0	•	•	0			1
		•	•	• •		•	ċ	•	•			<u>- 7</u>
• •		• 6	• •	• •		• •	• •	• •	• (<u> </u>
	0	• 0	0	0		•	0	•	0		:	Œ.
	•	•	•	•		0.	•	•	•			
	O	• 0	•0	•0		•0	0	•	•	:		<u> </u>
	•	•	•	• 0		•	.	• •			•	
	• •	• •	• •	• •	• •	• •	• •	• •	• •			. <u></u>
	0.	0.	o	0		•0	0.	0.	0.			
	•	•	•	• •		•	0	•	•			<u> </u>
	• •		1 0	P		•	•	•		: 1	•	T.
			• •				•	• •	• •			
		٥	0	•		0	•	•	•	1	•	· • • • • • • • • • • • • • • • • • • •
				STAGE								<u>.</u> 23:
	å	62.	O.	62.3	62.	62	Š	62.	62.			5
	662.3	662.3	662.3	662.2	662.2	662.2	662.2	662.2	662.2			. 2
		, c		2 2	529	62		62.	52.			ن عاد
1		2	i	500	25	2		52.	نې پ		:	1
	Š	62.	ċ	62	62	62.	~	62.	62.			<u>.</u>
	å	انۍ	٠.	3	63.	63.	'n.	63	63	;	•	
		6.3	÷.	3	6.3	9	•	•	•		•	. T
	٠.		E. 6	4 6	69	69	٠.		69:			<i>3</i>
) . - -	• ·	= =	2.5	2:	•	9				
	: :	70.		: 2	70.	0		69	69			_
		68.		67	٠	5		5.5	665.2			· · <u>F</u>

Linguistre

											1											;		•		1					:							:		•	:						50.0
											:							1											:									•		;	:						٩
			_			_																		:									:					:									\$. J
•	664.1	6.63	662.5	662.6	2.677	900	662	6.62.4	70.											•				i :	•					AUTO	6		:					•					:			:.	٠. د. د
•	664.2	663.5	663.0	662.6	4.077	0.704	662.5	662.4	400						:					:				•	• • • • •				i ; .	TAGE I	c		ı	LSTR	5	SPRAT	- C				;		:				• 06
	664.3	663.6	663.0	662.6	8 6 5 5	0.00	662.5	642.4	100		YOLUME	_	2924.	10.67	571.12	1022	1755			!				!	:					INAME IS	1					-		•		-				1	635.00		
	669.	663.6	66.3.1	46246	B . C . J	0.204	662.5	6.62.5	7. 760	•	LOIAL				:										******					JPRT	-		;	I PMP	Þ	1	00000			-	:				172.00		1.98
٠	<u>ب</u>	3.7	101	7.7		0	ຈີ	. I.	·,		12-HOUR	516.	15.	•		:	1755	•		0					٠		I NG			JPL T	0	AME	;	1001	5	×	0000								635 - 00	•1	
,	9.5	عد	cy.			2	'n	,	2		24-F0UR	714.	20.	10.63	200 00		1767.			AGE =					••••••	i	RAPH ROUTING			ITAPE	6	S HAVE S	TING DATA	ISAM	-	AMSKK	00000					SEL		؟! !! !ن	160.00		
	900										6-HOUR	_	30	0	•	1199	1078	•		HUM STORAGE)				•		HYDROGRAPH	REACH 2	į	IECON	0	ALL PLAN		IRES	-	1 40	5				- :	RLNTH 2300.			0 637.00		1.00
	9.675										PEAK									MAX I HUM					••••			Puls- R		1COMP	-		į	AVG			20				1	FLMAX 645.0		STA	00		.5.7
•	664.6	663.9	663.3	4.6.2.A		1.06.1	662.5	8-677	0.004				25.0		2		- 4 - 1 - 1								*****			ROUTING -MOD PULS-		ISTAG	A5			CLOSS		NSTPS	2					FLNVT			00 641.00 25		*
	664.7	664.0	66.30	6.6.2.A		4565	642.5	2.632	0.00				-	TATAL	•		THOUSE	2		i 		71.1	•		:			CHANNEL ROU					1	OLOSS					,)UT1116	:		:	COORDINA	.00 .0. no 212	1	
,	664.7	664.1	46.5.4	6,632		200	6(2.5	669.5	0.744		1							:	•	•		12 27	,		•••••••			H												DEPTH CHANKEL ROUTING		08623		SECTION	0.00 645.00 F0.00 172.00 E37.00 212.00	: 14 4	00.0
		_	-				_	-							,							2010		: :					:		:									DEPTH CI	:	0030		CROES	172		A 7. F
																						MAY TWITE)			į					1					:		•		TORFA	:		i	;		16 16 17	STORACE

		_	; ==:		 -	-	` <u>:</u>	<u>.</u>		<u>: :</u>	ĺ	` <u> </u>				(<u></u>	. · <u>. · · · · · · · · · · · · · · · · ·</u>		<u> </u>	<u>~</u>	تق.	·) T	, 		ī	<u>(</u>) 			E []]	r.	€.	ند	بع تت		O) 	-	
90			•																								·		•		•				*				!		:				
-			:					· · ·					:									-									:								•						
			1		:					:			1							:		1							:				:				:		1		,				
	. .	: :		0	202	. 4		2	2 1	5.0	, C 4	27.	15.	10.			•0	.	• •		: .		15.		~ 4		2.			•	•		35	35	635.03	35.	35	37.	9	2 %	0	639.1 637.8	9		
	.		15.	6	180	910	2	5	8	7 6	> 4		. •	.0.	•			.	• •		•		15.		D 1		6 0	•		÷.			35	35	7.E	35.	35.	37.	÷.	2 %	0	637.9	37	,	
	œ e	• •	13.	9	162.	• • • • • • • • • • • • • • • • • • •	52 B.	697.	5	= :	2 5	.00	-		•		.0	• •	• •		•	1.	S.	23.	0 1		3.	• •	1.	•	•		35.4	35.4	35.3	500	35.5	37.6	7.00	12.6	41.0	34.1	37.1	46.4	
	•	c ~	. 0	2		• =	2		75	3:0	7	r۸	1100	- 0	•		.0	•	• •				14.		- 0	• eo		• •		•	•		5.4	ان م. ا	5.0	5.3	5.5		9.6	2.7	1.2	39.5	7.2	F. 5	
	a . 6	c ~		64.	138.	6000	500 · • • • • • • • • • • • • • • • • • •	072. 1	82.		•		10	12.			• 0	•	• •		•	3.	13.	20.	32.	ح و ح	3.	٠.		•	• • •		5.4 ···· 6	5.4		5.3		7.3 6	9.4	2.R 6	1.4	38.3	1.2	. Y.	
	.		10.	5	1310	927.	. 88	245.	ر د د	i b	Š	37.	0	12.	0	STOR	•	•	• 6		.	10		18.	∾ ∾	9.6		. 5		•		STAGE	35.4 6	35.4 6	35.5	35.3 6	3500	37.3 6	9 2 9	42.9	41.6	3. T. S.	37.3	-	
	.		9.	37.	25.	13.	36.	2	72.				21.	13.	3.6		.0	•	• •		•	•	•	-	~ <	10.	-				. 0		5.4	6. A.	200	5.3 6	5	2.5	9.6	9 6.5	9 2		2		
	œ. e		9.		•	• •	. 10	3.	٠.		•	u n	i٠.	13.	7.			•			•	•	В.	-	~	12.	80	.		.0	•••					.		. ~		- B	6	A.7 654		-	
	•	•			•		• 17	257	-	•													• •	•	•			• ·		<u>.</u>	0:			63	9	63		3	63		5.	 		14	
		•	:	•	= :	150	374	275	120	21	1.1	c 4	2	•	•					!					er e				;				635	635	635	635	635	637	633	6.43	642	日 60 6 16 6 7	637	4.36	
		ř ~	æ	æ	6	7 5	0	2950.	2	7 2	~ 6	. O	25	ž.			0	6	ē		6		e ero	10 ·	о.		in the	~ -	-	ė (0			n, n		٠ د د	i i		e (2000 2000 2000 2000 2000 2000 2000 200		;	•
			i i												!									:					·						:		•						!	!	
		-18		~	!	-			•	-	E	- X		-	: ا		_	_	F :	<u> </u>	6	į,	~	· ·	•	_			:		2 6	T	1	·			-			· ·	: نيـ	<u> </u>	ل		,

•		1		* · · · · · · · · · · · · · · · · · · ·	•	:	•	•	•		-]]	1]					
		•		-	-	-	.,			•	} -								1		
			:	•	1					;				•		7	:			49 50	<u>.</u>
		6.3	635.4 635.4	635°5 635°4		435.4 635.4	635 • 5 635 • 4		635.5 635.4	635.5 635.3		635°5 635°3	635 • 5 635 • 3		635°4 635°3	635 • 4 635 • 3				<u></u>	<u></u>
ļ.,			1		CFS	3906.		6-HOUR	24-H	İ	72-HOUR 537.	:	VOLUME 107307.		:	!			· · · · · · · · · · · · · · · · · · ·		0
	; ;		-	Ĭ.	CHS INCHES	,		69. 9.09	11.00	i	11.09		3039• 11•09 281•71		:		:	•	•		<u> </u>
<u> </u>				THOUS CU M	CU H			1211.	18	12.	1823.		1478					; 			<u> </u>
<u></u>	:		i	•	1	-!	MAXI	HAXIMUM STO	TORAGE =		32.	1 1		;	:	: :		,		<u>قانت</u> ورس	
	HAX I MIH	HAXIMIH STAGE IS		642.9							1		: : :	<u> </u>			! !	; ;		 	- 5 - C

 ϵ

 \mathbf{C}

•

0

6

€.

		= :		.,			(• • • • • • • • • • • • • • • • • • •		<u>.</u>				. <u> </u>	13 (T) +	· <u> </u>	1111	<u> </u>				C	<u>্</u>	1		e, II.	6	. (د ر
# 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	90.5.	.5.6.5 			10 cm	35.7	35.6 35.6																						• • • • • • • • • • • • • • • • • • • •
642.2 642.5	Ψ.	Ψ,				9										4 4 4 4			ISTAGE IAUTO		LOCAL			X RTIMP 0 0.00	:			7 VUL= 1.86	
641.9 642.6	6.009	638.9	537.5	4.36.4	635.8	635.7	635°6 635°6		VOLUME	2924	10.67	1423	1754.		1	•			INAME IST		I ISAME	R96	00.00	NSTL ALSMX					202
641.7	641.2	639.1	637.9	636.5	635.8	635.7	635°6 635°6		HOUR TOTAL	ė 10						• • • • • •	_		JPRT		T10 ISNOW 000	B R72	0 0	STRTL CN 1.00			PīioP= i.oo	.ne HCUPS.	246.
6.41.5 6.21.5	641.4	639.3	0.57.0	636.5	6.35.9	635.7	635°6.	•	7.2		-	2/1		32.		4.	COMPUTATION	AREA 2	E JPLT		90 R	TA RA	0.0	A R 110K	PH DATA		0 - 00	0	275.
641.3	641.5	639.5	# 0 # v	636.66	635.9	635.7	635°6 635°6		-60		99 10.63	3.		STORAGE =		*****	A RUNOFF CO	RAPH - SUB-ARE	CON 1TAPE	H	1850A 11	PRECIP DA	3.00 132	LOSS DAT STRKS 0.00	HYDROGRAPH	-	RECESSION CORCSN=	ORDINATES.	3610
6.41.82 6.42.99	641.7	639.7	6.38.U	6.16.7	636.0	635.7	635.6		F-H0	142	8			MAXIMUM S		4	SUB-AREA	W HYDROGRA	ICOMP IEC		SNAP 0.00	P6	113.00 12	OL ERAIN	TINA	D	-3.00	OF PERIOD O	
641.1	641.9	639.9	5.07e.2	636.7	636.1	635.7	635.6			3700.		× +	- E			7		AMES INFLO	1STAG I		6 TAREA 2 2.80	PMS	\$2.70	01 TKR RT 10L			STRIGE	AC CHO	, E.
642.8	642.0	640.1	63F • 2	8000	136.1	6.35.7	635.7		ć	ב ב	INCHES	1. L	THOUS CU H		2.9	•		DEVELOP LAKE AMES INFLOW HYDROG	1		1 1 1 1 2 1 2 2 1 2 2 2 2 2 2 2 2 2 2 2	SPFF	0.00	STRKR D				-	702
6.00 F	642.5	540.3	C. XV.	50.000	636.2	635.7	635.7 635.6								15 64	•		DEV			Ξ			LROPT	,			1141	B 1 C 4
	.:										!				MAXIHUM STAGE				!			1					:		
		-						_	· ·	<u> </u>		<u>. </u>	<u> </u>	<u> </u>	. £		F 7 2		: :	7 B	2 8 3						· ·	; ;	

•			==			:			Ξ	Ξ	<u>말</u>	7 5		-					<u> </u>	T.E.		-		Ξ:				-:	17	I.		7	<u> </u>		_:_	2	<u>; ; ;</u>	E	<u> </u>	23		<u>.</u> .	-	17	<u> </u>		7	-
		:				:					:					;	: :															i !																
											:											:		,			:					:					•											
		1				ţ								٠			1					1												:			i		1									
		ט אנ	¥2	22	9370.		ב ני	9	വ	E C	9	م ن :	T F	3 E	5	92		6	25	# -			703.	۰.0		- 00	1	C	r c	u c	187.	-	•	 	145	13P.				Š		118.	113.	951	A7.	76.	99	
1:		2		•			- 1-		:	•		., .			,	.,		.,			•																							,				
		Loss	.02	• 02	-05	2.0	200	.02	.02	• 02	-02	-05	2 5	N: C	• 02	• 0 2	0	0	0.0			.02	• 05	200	20.	.02	• 02	.02	N (0	.02	~	0.0	> c	. 0	Ō	0	ء.د	: 0	•	•	•	-	00.0	•	•	
2		ĒXCS	.46	•46	• 36	90	900	.36	•36	• 01	0.01	.01	5 5	10	0.	• 01	Ö	• 01	0	10.		•	0	100	10.	.01	.01	.01			.0.	.01	• 01	0			. 0.		-	•	0	•	•	2 5	00.0	ç	•	
		A I N	8	48	e 6	500	9 60	~~	1	0	0.3	0 (5 6) c		c	0	0	o.,	. D.		.0	0	0.03	0 F	•	0	0	0.0	。 c	.00	O	0	بر د د	> =	, 0	0	0 0) C		0	0	9	> C	00	0	0	1
m,				~	'n.	.					:			;					j					آ ای	• •												:			0	ت	0	-	5.0	. 0	0	0	
•		PERIO	10	01	= :			01	=	10	1	= :	===		11	=======================================	=	==		12		12	12	12	2.6	121	12	13	P)	7 -	13	13	£ 1	13	7 -		•	-	1 -	4	1	*			15	15.	,	
•		HP . KN	ŝ	٠.	∵'		3.4	. 2	•	-	S-1	۳,		•	7	9.2	5	9.4	9	֓֓֓֜֜֜֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֡֓֓֓֡֓		0.3	4.0	٠. د د	7	1.2		1.4			2.2	ις. .Ε.	2 .	rc e	0 K	3.2	(L)	4 P		:	N.	m,	a u	r, c	1.10	~	~	
ę.	2	0. DA	1.01	.01		5	10	. 01	. 01	1.01	1001	: :	7.5		.0	10.1	1.01	1.01	: ::	55		.01	1.01	10.1	100	1.01	101	1.01	100	10.	.01	1.01	1.01	5.0		.01	.01	. o.	200	- 02	- 05	ر د د	20.5	, c	00	÷ 05	• 05	-
	מים בי																	•							-													•					- •	!	. •			
	•	0	e		x (. «					æ e	E e			œ	80			œ. c					•		98	8		• c		8		œ	• • • •	• •	89	œ a							63.			
	2	NO.	,																				•																-				_ •	:	-		~	
•		1055	0	0	20.		> c	•	.0	0	0	0	9	3 C		•	ø	0	0	2.5	> c	0	0	0	96	0	0	0	0 :0	- -	0	10	0	0.0	>	0	0	0 0	3 (C	. 0	0	•	0 0	- :c	. 0.	0	0	1
•		Excs	•	•	÷	916	•		:=	٠,	9	•	•	ء د	•	: =		•	9:	•	? 5	10	0	9	•	•	0	•	9	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֡֓֓֓֓֡֓֓֡֓֡	. =	0	0	0:0	•	•	0	•	-	0	_	•	0 0	-	.03	0	•	4
Ξ		NIN.	. ~	20	20	210	2 6			02	02	20	200	20	20	05	02	20	05	2 5	, ,	020	02	05	2 6		0.5	05	20	v °	20	02	20	50	ט גר	50	60	in in	3 (C		0	•	0	5		0	0	
12.		, az		:		İ			:		0	-	~ •	7	. IL	ت د	1		6	٠,	- 0	1 20	•	2	£ r	- cc	6	0	- (v r	· •	3	S.	~	20		1	۰.	2	··c	æ	1	ec. 6			2	·	
		PERTO		-					1		-				• ~	-	-	-		o c		12	~	~	~ ∘	, (V	2	€0	P7 - W	o ⊷	נים ל	3	m)	,	r in	.	-	* •	* 4	•	4		e i	er č	מי	ur.	ເກ	
		HM. WH	.10	~	* , .	Ø : b	<u>ر</u> ۾	: -	. ~	. "?	•	\$	٠.	• "		•		•	Ξ.	٠٠	•	. K	•	7	۲,	•		•	٦,	٠,	•		•	٦,	١,	•	Ş.	ė.	ຸ. ເ		*	ن و	ç.	- :	8	*	4	
	c	0.0A	1.01	•	-	•	9 9	? ?	-	•	0	· •	• •	? .c		•	•	0	0	e .	•	0	•	0	•		.0	9	•	? ?	? •	0	•		•		ō.	0.0	•		Ę	•		? 5	1.91	0	10.1	
		Ě	-		,	1	,			. •			٠			. •		-	7	•		1					1		,			i i	•		-	•		•					. •				. •	
		1												:					!					:			İ		i			i i		,										;				

	,					:
# C W	90 0 H H H	2000	, , , , , , , , , , , , , , , , , , ,	« • • • • • • • • • • • • • • • • • • •	8.8.8.8.8.8.8.8.8.8.8.8.8.8.8.8.8.8.8.	
	00000					
	00000					•
000	00000	••••••				20 ME
154 156 159	2	165 166 160 170 171 173	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	11111111111111111111111111111111111111	1996 1996 1996 1998 1998 200	01AL VOLI 23235 657 216 516 544
~ ~ ~ ~ ·	# W C C C C C C C C C C C C C C C C C C	N 4 N 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		6.30 6.40 7.50 7.50 7.50 7.50 7.50 8.00	ΚΒΘΣΡΟ •••••••	HOUP 1 162. 33. 1.000
1.02	11.00.00.00.00.00.00.00.00.00.00.00.00.0		1.02	000000000000000000000000000000000000000	200000000000000000000000000000000000000	10 72-10 10 10 10 10 10 10 10 10 10 10 10 10 1
320.00	ស ស ស ស ស ស ស ស ស ស ស ស ស ស ស ស ស ស 	445 441 441 441 441 441	65 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	9829. 829. 6475. 868. 868. 868.	24 4 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	24-HO 161 21- 21- 31- 31-
	, , ,	a a c a a a a a a		222222222222222222222222222222222222222		6~HOUR 5559. 157. 18.47.
:	:			W W W W W W W W W W W W W W W W W W W	200000000000000000000000000000000000000	PE AK 9824. 278.
សារស្ពេ ១៩៧		 ១០០០១០០០១ ១៩១១១០០០១	ଟ ଟ ଟ ଟ ଟ ଫ ଲ ଲ ଲ ଲ ମଣା ମଣା ମଣା ଟ ଟ ଟ ଟ ଟ 		min (V 00 t	CHES OF THE SECOND
	5.55.6	とうしゅ りょうちょう ちゅうりゅう ちゅうしゅう	4 5 5 7 7 7 7 8 8 8 9 7 8 8 8 9 7 8 8 8 9 7 8 8 8 9 9 7 8 8 8 9 9 9 9	\$	94 95 94 97 97 98 90 100	Ž
		2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	0 14 4 1 D - 0 10 10		41.047.04	
					10.00.11	

,

48. 184. 184. 185. 3041. 167. ISTAGE JFR1 421. 1738. 3673. 3584. 1237. 72-HOUR 581. JFL T COMBINE SUB-AREA 1 & SUB-AREA 2 FLOW CONTRIBUTIONS COMBINE HYDROGRAPHS TAPE 254. 2811. 2811. 1698. 299. 1F CON 1COMP PEAK 4912.

CHS

THOUS CU M

ISTAB

C

(

 \hat{C}

FOR

IY DR DER APH

25.00 2000 2000 25.00 25.00 25.00 10.00 10.00

<u> </u>	Ð			3	_			- :-		· - =		<u>C</u>	-			,				ر 11	- 301		_			^	;y- ·		` :20				(-	_7.	(` :	- ;- - ;-	<u>^</u>		(\ 	((- ·	6	<u>-</u>		0	·•	٦
		į						:			•						•												,						,																
		:						!																																											
:								:																											:																
:					1			1											;						:				•						:					:		,	:								
:					: ;			1						ĺ			:					•1			:															-			: .								
-	14.			12.	٠,	207.		. 0	: α	· œ	۳,	_	~	. =	64.	32.	19.	14.	=										ļ		14.		2.5	12.	- I 🕿	•	2	48	60	ر د اد	9	24 A.		62.			20.))			
:							-		•	. v.	. ~	1																							-		-	•	α :	in ic	•				٠						
	•	PO -0	N C	31 N	9	279-	- ~	377	4	383	35.5	747	9	57	• 69	34.	20.	15.	12.	:		:			:						• 1	13.	vσ	7 to	.0		870	297	532	390	ง กล	_	65	ac. (20.				
:					1				•	ۍ .												:			:		:		!			•						. LO	-	٠,٠	ŭ				:						
	4		~ 0			1730	2	200	77.4	786		836	315.	. æ	75.	36.	21.	15.	12.		5	5 6	Ç			3797.	:				• •		12	v =		<u>ن</u> ت	8	98	1	0 6	0	273.	2	•	24.	• 6	20.	ı	0LUME	2.5	0.70
į pro	,	;			į				•	· •	. ~	!									227	v	- ۵	2.7	:	נאו נ	:	1	!	m		1			!		:	m	، ي	E io	•								AL VO	•	- ;
RIIO	4	13	N	 		156.	. 69	, -	• •	1 1 1	123		341.	178.	P1.	38.	22.	15.	12.						:		:	1	•	R110		- C	Š	28.		58	999	8.5	<u> </u>	د بر د کار	2		~ (2.4	22.	20.		101		
 2	•	,						P 7	ט כ		; ;)		:			;		;			- 5	֓֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	•	7 2	797	-		i Ii	×		•							Œ i	- 1	•				:				H0UP 037.	•	۰.
11d		M) : (N 6			158.	- 61 4	. 4	, .	·	, R	. 0	370	188	P9.		23.	16.	12.		-21	-	-	2,0) ((1)	`		:	י פרא	÷ :		12,	2 5	158	246.	•	····	343	~ 10	946	299.	188.	• •	24.	22.	21.		7:7		- ;
×	:				1			Î		, ~	- M	-					:		į	!	707	4	, מ	9	2	785.				4		•						N	in f	-	,	:			•			:	518.	÷,	0.65
TA	-		2 :	15.		242	u π.	: 3	7.0) M		164	•	10	97.	-		16.	13.	1	-42	-	-	2,		. IN	1			,		215	120	1		32	38.5	9	779		919	N.	ຕະ	- 0	210		21.	į	24-		- 5
RAPHS		1			1			1	, 4	- α	. .	-					:				- HOUP	C 4	7			172.				SHLE		:					,	~	40		,	:							HOUR 158.	-	5.
YDROGI	14.			• • • • • • • • • • • • • • • • • • •	,	230	0					323		10	0	-		-	13.	'	ė u	9		K.		, 6 2			i . ::	YUROGR	5 r	O IN	2 0	. P	3	16	39	5	10 d	ع زد	8	327.	<u>د</u> د	۲ × د د	2.5		21:		<u>.</u> .	1	Č
F 2 H		1		:				-		. =	•	-									7E.A.K	9. e	• • • •			•			1	~		i					1	N.	~ c		-	•			1			: ;	rr AK r.0.7.	2	
SUR OF	4			2.	. :	20.4) <u>-</u>	3.E	, ,	יע עיי	291	. 2	487	٠.	15				13.		۰				1					SUF OF			12	: ~	2	6	313	191	ני ניכ	0 in 0 in 0 in 0 in 0 in 0 in 0 in 0 in	255	347.		- 4	25		21.		E		
		1						-	• 4	- 03	•	-					:		,		,	ָ	C H L	<u>.</u>	AC-FT	. E		!		,								_	e r 0	ک ا حد	•				:				Ç	CHS	RCHT'S
:			20	12.	:	ں ع	. =		` a	610	9	70	33		S		. a	8	14.	! !		,	=	=	•	HOUS	;	f	,	•		7.4.	12:	2 2	96	ű,	5	Z :	2 5	- 10	7	381	3.5		26.	23.	21.				2
		1) <u>2</u> 0		-													:	•	,								:		,	- '	בניק	1 141 C	-										
	€ ~	7, P		12.	,	2 6	1 V E 0		, ,	4 6 6		910	•	5	36	59.	30.	0	14.	!					:				:	:	- *		٠.	. ~		9.3	295	282	9	7 7 2	72	431.	~ P	, א ה			21.				
								:	۰,۳	; ex	. 15			:													1	i										(ma	e auc -	-										
-					į			:												, ; [:		:	:							!					1					•						
				!				-						-								:			:		:		:					٠						:					!						
<u> </u>	2.7					_	<u> </u>	1			:			<u> </u>						Ļ	.	! ;	. .	 ,		· ·		┦.	1	Ξ-		-		Ţ	i !-	_	j	_	<u></u>			· ·			1		: : :	: :		: !	ξ.

1	- 		7			C EET				· F143	<u> </u>	. ==:			<u></u>
I								: •		:			•		: : : : : : : : : : : : : : : : : : : :
	,		:		:	;			641.00	7140.00			:		
	-	*****			IAUTO				640.00	4618.00		1	!		
					E ISTAGE			A ISPRAT	639.00	2621.00	280.	641.	EXPL 0.0		
		••••••		4	JERT INAME	:	0 0	TSK STORA 0.000 155.	637.60	779.00	236.	639.	CAREA 0.0	UÁMUIÖ 0.	WSEL FAILFL
	: :	•	TING		JPLT 0	A	- B	0 000°0	637.40	633.00	203.	637.	ELEVL COOL	COUD EXPO DAI	
-	-	••••••	HYDROGREPH ROUTING	LAKE AMES	N 1TAPE 0 0	LL PLANS HAVE	S ISAME 1	6 AMSKK 0 0.000	637-10 63	483.00 63	. 197.	. 637.	EXPU ELE		DAM BREACH DATA
	:	•	HYDR	_	1COMP 1FCON	~	AVG IRE 0.00	NSTDL LAG			1. 166	5. 636.	0.0	T0PE1	08410
		• • • • • • • • • • • • • • • • • • • •		ROUTE INFLOW HYDROGRAPH THROUGH	151AQ 10		0.000	NSTPS NS	636.20	200.00	155. 161.	5. 635.	EL SPUID		
.!	,	•		TF INFLOW	1 m m m m m m m m m m m m m m m m m m m	1	0.0 0.0		635.20	19.00	47. 15	8. 635.	CREL 634,9	:	
	•	• • • • • • • • •		ROU	i i	:			634.90	00.0		N= 628.	ŀ		
			-		; ; ;			:	STAGE	rlow	CAFACITY=	ELE VATION=	:		
I		~ -				= = =	e - •	-	= 1		· ·	· ·	:		

CONTRACTOR OF STREET ACCUMULATED FRR OR (AC-FT) THE DAW PREACH HYDROGRAPH WAS DEVELOFED USING A TIME INTERVAL OF .021 HOUPS DURING RREACH FORMATIC DOWNSTREM CALCULATIONS WILL USE A TIME INTERVAL OF .167 HOUPS. THIS TABLE COMPARES THE HYDROGRAPH FUR DOWNSTREAM CALCULATIONS WITH THE COMPUTED BRFACH HYDROGRAPH. INTERMEDIATE FLOWS ARE INTERPOLATED FROM FND-OF-PERIOD VALUES. ACCUMULATED FRROR (CFS) 155. 151. 156. 158. 1113. 1113. 1118. 126. 882. 1991 1992 1993 1993 1993 1994 90 195. 191. 189. 191. ERROR COMPUTED BREACH HYDROGRAPH (CFS) INTERPOLATED EREACH HYDROGRAPH (CFS) 1816-1933-1991-1991-20169-2279-2279-2359-640. 715. 752. 790. TIME FROM PESTANDE OF BREACH (HOURS) 021 518. 518. 518. 518. 618. 618. 618. 3.333 3.588 3.708 3.729 3.771 3.229 3.250 3.271 3.292 3.375 3.792 3.813 3.833 3.854 3.854 3.20A 3.896 1811

•

 \mathbf{C}


0

6

•

0

(



	10.	0000	10.	10. 111. 66.	111.	10. 12. 87.	10. 13. 97.	10. 107. 199.	10. 116.		:	
mne	200	4000	270. 1836. 4132.	2410. 4466. 8225.	316. 2366. 4969.	355. 2(12. 5605. 7453.	412. 2902. 6331. 7043.	490. 3129. 7076. 6643.	628. 3332. 7725. 6241.	:	:	**************************************
£. ⊶	781 781 530 292	5 4 6 7 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	S S S S S S S S S S S S S S S S S S S	Col Co Col Col Col Col Col Col Col Col Col Col	240	3394. 876. 320.	2990. 768. 360. 218.	2617. 702. 341. 207.	2343. 532. 323.	!		
	40000	176. 99. 29. 23.	2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	161. 86. 27. 23.	152. 81. 39. 27.	14. 37. 26.	136. 70. 35. 25.	2.00 % % % % % % % % % % % % % % % % % %	22. 22. 25. 25.	:		* * * * * * * * * * * * * * * * * * *
i :	555	· · · ·	156.	STORAGE 156.	156.	156.	156.	156	157.			
	31 CO CO CO CO CO CO CO CO CO CO CO CO CO	100 K B)	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	158. 158.	158. 158.	158 • 159 •	158. 158.	158 158	158. 158. 160.			<u>, à f à . E . </u>
i	S ~ E	555	9 - 6	165. 175. 185.	42 25	168. 177. 189.	948	170. 179. 197.	~ = 0	,		· <u>* - : - : - : - : - : - : - : - : - : - </u>
	198	- 50	O 10 0	228. 256. 289.	232. 261. 286.	2564 2674 2834	239. 273.	242.	285. 272.	•		<u> </u>
!	9 27 90	1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		2 to 10 is	2 2 3	203.	207	205. 188.	2000			
186. 179. 170. 169. 162.	185. 178. 169. 167. 162.	184	1669 1636 1636	1880 1750 1630 1630	179 179 163 163 161	181. 174. 166. 163.	181. 173. 166. 162.	1800 1720 1650 1620 1620	179. 171. 165. 162. 162.			
		4 10 10 th	634-9 635-0 635-0 645-0	57AGE 634-9 635-0 635-1	No. No. No. No.	10 10 10 10	សព្រហ្ម	80 80 80 80 80 80 80 80 80 80 80 80 80 8	1	1	•	ı
1		(名) (名) (名) (名) (名) (名) (名) (名) (名) (名)	in in a color	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	S S S S S S		் மைவை	M W W W W			:	
ර ගියි කිරි :			4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	641.4 641.4 641.4	0 4 4 8 8 8			0 4 4 W	0.000 000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.		•	,
. W W W W W W W			6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		ကြောက် ကြောက် သော လေသောက် သော လေသောက် သော လေသောက် သော လေသောက် သော လေသောက်	យស្ចេញ មេ ស្ត្រីស្ត្រី ស្ត្រីស្ត្រី ស្ត្រីស្ត្រី ស្ត្រីស្ត្រី ស្ត្រិ ស្ត្រី ស្ត្រ ស្ត្រី ស្ត្រី ស្ត្រ ស្ត្រ ស្ត្រី ស្ត្រ ស្ត្រ ស្ត្រ ស្ត្រី ស្ត្រ ស្ត្រ ស្ត្				;	· · · · · · · · · · · · · · · · · · ·	

€÷

 \mathbf{C}

•

56. 10. 115. 114. 709. 3298.

10. 10. 13. 13. 196. 196. 1972.

	;	7.	6	10.	12.	e u	166.	399.	3050.	601R.
	N.		•	10.	11.	P.	176.	346.	2917.	5329.
<u>></u>									3005.	-
OUTFLO	5.	9	o .	10.	11.	£1.	156.	284.	2945.	4346.
	5	• 9	å		11.	c e	197.	267.	2472.	4031.
	-	• 9	œ.	10.	10.	36.	134.	254.	1949.	3775.

A9. PLAN 1. RTID 3 STATION

MAXIMUM STORAGE = 26.	_ ^	<u> </u>
MAXIMUM STORAGE = 26.		
MAXIMUM STORAGE = 26.		
MAXIMUM STORAGE = 26.	1	
MANIMUM STORAGE = 26.	:	
HAKTMUM STORAGE = 26.	<i>i</i>	
HAKTMUM STORAGE = 26.		
NANTHUM STORAGE = 26.		
HAKTMUM STORAGE = 26.	ł	!
HAKTMUM STORAGE = 26.		!
MAXIMUM STORAGE = 26.		
MAXIMUM STORAGE = 26.		
MAXIMUM STORAGE = 26.	! :	: !
MAXIMUM STORAGE = 26.		1
MAXINUM STORAGE = 26.		
MAXIMUM STORAGE = 26.	!	
MAXINUM STORAGE = 26.	: :	•
HAXIMUM STORAGE =		
HAXIMUM STORAGE =	i	
	3	
		-
	# 9	
	TORA	i
	ST MIN)
	*	
		:
	:	
	1	
	i	
1		
	<u> </u>	

erdental arra

ŀ

نب.						- , -	<u> 1</u>	· <u> </u>	=_	-	٠ _3	1-		=.5	.÷.	<i>:</i> _		<u></u>				- 7 -	J.;	· -				- 1	- <i>:</i>	<u>عب =</u> !	-		Ţ.		Ē			24).	_3_3	· <u>· ·</u>		Z ,-		· \	-	••	-	ئ ـة	-	<u> </u>	-	<u>.</u>	<u> </u>
Š													:												:					:													:								:		
													i						:								:			:											:												
		:		;									:			:						1			 		:											:					;						1 1 1				
æ o	10.	15.	-	_	r:	3284	9.1	32	2	•	2	0	S	61.	33.	25.	22.		2	• •		•		•	-		11.		50°		• •	•	-	•	•	•	•		•	16	•	10.	10.	::	2	3	40	19.	2	13.	612.6	-	-
÷°	10.	13.	0	5	172	3083.	9.5	722	70	_	4	0	W):	•99	34.	25.	22.			• •		•		-	•			22•	 (• -	•			•	ė	•	:	6	6	10.	10.	9		•		- 0	19.	7	13.	612.7	2:	:
. .	10.	12.	•	=	•	2P27.	-	~ (cc. 1	8	£	~	•	72.	36.	26.	22•		. 0		•			•	1	2.	σ.	19.	22.	٥ı٢	• • • •		-	:	•	•	•	:	ċ		•	ċ	ċ	. .	.	, N		6			612.7	ů.	-
- 6	10.	11.	85.	-	4	2553	965	537	4	0	æ	2	146.	-	38.	26.	22•			• •					1.					Vir			-1			•0	•	:	-	. =	ċ	ċ	ė	<u>.</u>	<u>.</u>	ů.	• •	. 0	:			612.1	_
6	10.	11:	73.	166.	₩)	2304.	T ()	σ	₽.	0	+01.	242.	154.	82.	* 0 *	27.	23.		-	•				•				16.		ウャ	3,0					•			101	10.	10.	10.	0		=		10.	20.	ď	:	612.9	12.	11.
. 6	10.	11.	61.	£3.	ನ	2044.	5	23	20	2	n	10	•	88.	43.	284	23.	acto	2			0			-	1,	7.	•	25.	- 4		•	1.	1.		0		CTACE	10.0	10.1	10.2	10.2	10.2	10.9	11.6	12.4		20.4	1 R . S	15.2	6.13.0	12.2	11.7
£ &		11.	0.	•	26	0	20	6	691	5	S	٠	10	•	45.	8	*			• •		0.			:				26.	0		: :		-:		•	:		ċ			÷	•	<u>.</u>	<u>.</u>	•		:			613.1	•	•
ν ec	_	10.		39	254	•	2.5	566	9	602	6	5	~	5	43.	•	24.		-						1.	-:	5	-	26.	اوا ڪ			1	1.	•0	• 0	•		0	10.	10.	10.	10	•	::			20.	7	15.	613.2	12.	:
₽. e¢		10.	2	7	241	¥	ت. تو	4 5	2	846	2	•	96	8	52.	0	•			•					1.	:	•	2	26.	CIN	• 6		•	1.	•0	0	•	: : : : : : : : : : : : : : : : : : : :	ď			ċ		•	•	•				٤	613.4	٠.	-
ι		10.	17	52	23	111.	8	25	19	2	90	Ξ	92	15	10	•	•				• •						₩)	=	25.	٦.٢			-		9.	•0	•		ć		ċ	:	;	.	<u>.</u>	٠.		:		÷	613.6	٠.	
		;																	-	•		•														:					i ;					1					:		
							-			•	!			, 											:					1						:		1							٠	1					;		

81												•12 2•n2	703-74 23657-32	614.21
610.5 610.5	!											1.74	550.70 19405.17	613.63
610.6 (1) 610.5 61 610.5 61		:				IAUTÓ					!	1.49	456.80 15639.65	613.05
610.6 610.5 610.5	VOLUME 218975. 6201. 10.68 271.17		;			INAME ISTAGE	LSTR	STORA ISPRAT	,	:	00•00	1.25	366.85	612.47
610.5 610.5 610.5	TOTAL	1 :				JPRT IN	IPMP	TSK S1			253.00	1.05	281.73 5488.26	611.49
610.7 610.5 610.5	10 72-HOUR 1095- 3- 1095- 55 10-68 54 271-17	:		7 1 NG		E JFL T	E SAME ATA I OP I	0 00 ° 0 0	:		00-609-00	0 %	202.64 7062.19	611.32
610.7 610.6 610.5	5147. 24-HOUR 5147. 1517. 146. 13. 9.03 10.55 229.47 270.54 3.557. 3009.	STOPAC		HYDRUGRAPH ROU	513 BRIDGE	TECON IT APE	L PLANS HAVE S ROUTING DATA IRES ISAME	LAG AMSKK		РLИТН SEL 6001600	EVETC 614.00 240.00 620.00	D	131.27	610.74
610.7 610.6 610.5	PEAK 6-H 2456 51 2456 51	MAXIMUM		:	PULS- NJ	1COMP 1	AVG 1	NS TOL		620.0	240.00 240.00 353.00	5.0 0.0	. 11. .64	610.16
610.8 610.6 610.5	CT CT CT CT CT CT CT CT CT CT CT CT CT C	3		•		15TAO A10	S CL 088	NOTES		FLNVT 609.0	5	.35	.94 3410	.5A
610.8 510.6 610.5			620.6	4	CHANNEL RO		0000	! !	ROUTING	0463	TION COORDINATE F20.00 120.00 614.00 353.00	6 8	2 23.3	609 0
610.E 610.F 610.5	• •		بيا	•	•				CHANNEL	.0360 .0462	CROSS SECTIO 0.00 F2 253.00 61	0.00	1245.	Knc.00
		· }	MAKIPUH STI			:	!		NORMAL DEPTH	•		STORAGE	OUTFLOW	STAGE

		QL.	.	9.	10.	15.	113.
						13.	
		•		9.	10.	12.	• 4 6
n		·M		9.	10.	11.	£3.
A10+ PLAN 1+ RTIO 3					•	::	
A10+ PL	OUTFLOW	.	ů.	ŗ.	•	11.	61.
STATION		-				::	
			÷	œ	10.	10.	36.
		:	ų.	œ	10.	10.	25.
		-:	;	Œ	• 6	1 n.	17.

5:

v i) • i) v

619.42

f 18.84

618.26

703-74 2365.7-35

550,70

456.PP 15639.65

366.PE 12340.72

281.73 9480.26 (17.6R

202.64 617.11

131.27

3410.64

1245.-22

2014

616.52

615.95

615.37 23.27 2148.94

614.79

227. 1107. 3418.	241.	5: 1 No. 1	C	284.	309	• : • 0	7		_	
25.25	0									
523		5	468	2941.	300P.	C .	•	ت ت	_	
2	Ę	•	4029.	4343.	4771.	5354	13	6843	7599.	
9	56	570	4	F276.	7941.	T)	115	7	_	
ž	Ę	17	┏.	4 35B	3956	576	258	964	æ.	
17	Œ.	ព ខ 3	_	162R.	1495.	ν,	239	2	•	
3	53	7.80.	713.	656.	602	556	511.	475		
'I	- :		334	315	242	27.9	3		<u>, </u>	
2	9	₹.	186.	176.	165	156.	•		1 1	
Λ.	114.	a . ,	5	96	96	ž.	5 6	Ξ,	N 4	
5	• 29		58	26.	55.	.15	ĸ.	9 9	• • •	
42	0 4	38	36.		•	• • • •		*0°		
Œ	27.		25.	25.	24•	23.	55.	22.	21.	
		-		STOR		:		•		
0	•	ć	ċ		•0	•	•	•	0.	
0	0			•	•	•	•	•	•	
			.0	•0	•	•	•	•	•	
ċ		•	•		•	0	ځ	•	•0	
6	0		•	•	•	• 0	•		• 0	
			•	•	•	•	ô		•	
		•	•		•	•	.	.	•	
			• 0	•	0	•		•	•	
	•		.	• •	•	• •	• •		• •	
• •		<u>.</u> -	-		• •	-	: -	-	• •	
	•				•			. 0	0	
									•	
•	•			0		•	ò	0		
		•		0	•	•	•		•0	
				•0	.	0.	٠ ۵	•0	0.	
•		•	•	•	. 0	• 0	•		0	
	ė,	•	o ·		.	•	.		•	
		•	• •	•	• •	•	• •	•	•	
•		•	• 0	•	•	•	•	•	•	
				STAGE	t.J					
9	6	60	6	. 60	09.	.60	6	6	•	
6	6	60	6	60	0.	0.	.60	•	•	
ċ	6	. 60	6	60	60	60	60	6 (•	
•	÷.		6:6	• 6:8	60	609.3	609.3		609.3	
•				, ,						
•	: :		: :		: :	-		-		
•					2	12	•	ראייו		
÷	5		ı,	15.	15.	15.	5	S.	5	
5.	•9	16.	٠	9	16.	616.6	16.	_	۲.	
:		7.		7	17.	17.	17.	~	œ	
ě	£	16.	·	9	16.	٠	12	ഴം	no.	
ů.	ů.	Š.			# (I	•	14.	•	•	
٠,	•	*	:	•	13		13.	n,	Ν,	
٠.	٠,	2.		_	12.	Ξ,	::	- (~ 1	
• •			.	• 		• •	•	- (> c	
7 TO 7	7 - C - C	0 - 0	f.10+0	610.0	6.01.0	6.007	•	2*014	210-5	
• -		• • •	• •	20			0	` •	` •	
٠,	• (•	•	2.1	• •	•		٠,		

Ç

؛ ي		OTS CKS INCHES	8570. 243.	5216. 148. 9.15 232.53	1600. 45. 11.23 285.27	1154. 33. 11.26 285.90	:	230866. 6537. 11.26 285.90	
7-		AC-FT THOUS CU M	:	2586.	3173.	3180.	- :	3180. 3922.	
	• • •								
~			MA	MAXIMUM STORAGE	AGE =	1.			
	MAXIMUM STAGE IS	617.5					:	,	

<u>(</u>										'n					1 .				:			:			:					1.17 1.39
611.3 610.7	610.0	6.69.7	609.6												1	•		•	0		!					:				. 96.
612.3 £11.4 £10.7	610.1	2.609	609.6 609.5									:	-		:	•			STAGE JAUTA		LŠĪŘ 0	14 1000	≪ Y	•		•	,			.16
612.5 711.4 610.8	610.2	409.7	609.6	VOLUM	218974.	6201	10.68	271-17	3016.	3720.						• • • •			INAME		•	i	1 · 1 ·					0 60K.00		
612.6 611.5 610.9	610.2	6.09.8	609.6		095	31.	99•	.17	.016.	20.					•	• • • • • •			JPRT		ÎPNP 0		0 • 0 0 0				:	.00 105.00	•	£7.
6112.7 611.6 610.9	510.3	609.8	609.6	72-			10	271	30			-1				•	CUT ING		0 0 0	E SAME	1 00 1	İ	0.00 0			,	:	•00 + 00•	,	# (
6112.9 611.7 611.0	610.3	609.R	9.609	UR 24-HOUR	}					8. 3712.		STORAGE =					HYDROGRAPH ROUTING	4	CON ITAP	PLANS HAVE S		-	000.0			ILNTH SEL	• 01	4.00 P0		.30
613.1 511.8 611.1	610.4	60609	9.609 9.809	- 5				229	255	314		HAXIMUM				•	E	ULS- REACH	ICOMP IE	ALL	AVG 1	10 + 101	0 0 0			LHAY	18.0	V . STA . F.L.		
613.3 611.9 611.1	610.4	6.604	609.4	• •		MS 24:		**	11	Σ.		:				• • • • • • • •		-H 00 P	ISTAG A11		CL 055		<u> </u>	•		ĒLWVT Ē	9 0.109	STA		۰
613.6 612.0 611.2	410.5	6.694	609.7		ت	CHS	INCH		AC-FT	THOUS		:	7.6	•		•		CHANNEL ROUTING			ÖLÖSS 0.0				001186	0N(3)	.0300	SECTION COORDINATES		40.
613.8 612.1 611.2	610.6	610.0	609.7	•						1			17 31	2		•		S.	1					,	٠;	2)40	0070. 0			0.00
,	•									:			MAYTHIN CTACE	3								•			WORMAL DEFIN CHANNEL	CLING	00.00	.		STORBER

G

9								:		•				. ~
	606.6 406.4	6 606.4 4 606.4	606.5		606.5 606.3	606.5 606.3	606.3 606.3	606.4 606.3	606.4	606.4 606.3	606.4 606.3		<u>.</u>	· ·
G.			CFS	PEAK 8572.	6-HOUR 5216.		UR 72-HOUR 0. 1154.	;	AL VOLUME 230863.					C
<u> </u>	-	. Z	CHES FM C-FT		9.15 232.52 2586.	11.23 285.27 3173.		11.26 285.89 3180.	285.89 285.89 3180.		: i			\overline{C}
		THOUS CU H	E D	• .	3190	1			3922.			•	<u> </u>	C
					MAXIMUM SI	STORAGE =	•				:			\dot{C}
	MAXIMUM STAGE IS	615.4					r Sections in the second	**************************************						

| | | | | | | | | | | |
 | |

 |
 | | | |
 | - | • | | |
 | | - |
|--------------|---|---|---|---|---|---|---|---|---|---
---|---
--
--
---|---|---
--	--	--	--
---	--		
 | <u> </u> |

 |
 | | |)
حجاج |
 | <u></u> | —————————————————————————————————————— | | | E:
 | • | 0 |
| - | - | <u>-</u> | | | <u> </u> | ئے د | · · | <u></u> | <u>۔۔۔</u>
، | : <u>=</u> | نــــــــــــــــــــــــــــــــــــــ
 | ا ــــــــــــــــــــــــــــــــــــ | <u>5.7</u>

 |
 | | 7. <u>F. 4.</u> | أحت | _: .* _=_
 | ئبد۔ | ىلىقاقات | | 811 2 121 | تتلت
 | LLL.I | |
| ! | | | | | | | | | | |
 | | 1

 |
 | | | | | | | | | | | |
 | | | | |
 | | |
| | | | | | | | | | ٠ | |
 | | ;

 |
 | | | |
 | | | | | •
 | • | |
| | | | | | | | | | | |
 | | •

 |
 | | | i | | | | | | | | |
 | | į | , | |
 | | |
| | | | | | | | | | | |
 | | ;

 |
 | | | | | | | | | | | |
 | | | | |
 | | |
| | | | | | | | | | | |
 | |

 |
 |)
1 | | : | | | | | | | | |
 | | : | | |
 | | |
| : | | | | | | | | | | |
 | | :

 |
 | | | i | | | | | | | | |
 | | í | , | |
 | | |
| ! | | | | | | | : | | • | |
 | | i

 |
 | | | | •
 | | | | | i
 | | |
| : | | , | | | | | : | | • | |
 | | İ

 | į
 | | | | :
 | | | | | r
 | | |
| æ | • | • | <u> </u> | ٠, | | n | • | | , | |
 | |

 |
 | | | | :
 | | . | ; | | | | | | | | |
 | I | : |
| 80 | .07 | 0 | 200 | 9 | 90 | 90 | • | | 1 | |
 | I |

 | !
 | | | | | | | | | | | |
 | | | | |
 | :
!
(| + |
| . | · · | 9 | • | o 4 | ۍ د | 9 | | | 1 | |
 | |

 |
 | : | i | i | 00
 | | 1 | 1 | | | | | | | | |
 | į
1 | |
| | | | | _ | | | | | į | |
 | | !

 | į
 | • | | | AUT
 | | | : | | | | | | | | |
 | | |
| 6.0 | 8.0 | 5.5 | ֡֡֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֓֡֓֡֓֓֡֓֡֓֡֓֓֡֓ | 6 4
5 5 | 6.5 | 6 • 3 | | | 1 | |
 | |

 | ;
 | • | | | | | | | | | | |
 | | | • | |
 | | |
| 9 | 9 | 9 | 9 | ב
פ
ע | 9 | 60 | : | | | |
 | |

 |
 | : | | | | | | | | | | |
 | | 20 | -0 | |
 | · | |
| : | | | | | į | | | | | |
 | : |

 |
 | | | ļ | JA
 | | LSI | PR | | | | | | | | |
 | | |
| - | بّ | ស្ដ | Ņ. | <u>ر</u> ي ع | - | 'n | بي | • | | <u>~</u> } |
 | : | ļ

 |
 | ; | | | 13
 | | | 15 | |
 | | |
| 9 | 98 | . 0 | | 9 9 | 90 | .90 | 5 | 971 | 203 | 5 | 910
 | 720 |

 | :
 | 1 | | ! | ٣~
 | | ! | 8 4
• | |
 | | |
| ع ، | £ | 9 | ~ | ک ع | , . | 9 | | | • | ָר רָ | - M
 | ;
; | į

 | į
 | : | | İ | N N
 | | | 510 | | | | | | | | |
 | | |
| : | | | | | ; | | TAL | | i | |
 | |

 |
 | | | | 1
 | | | | | | | | | | | |
 | | |
| | 8.1 | 7.6 | 7.2 | 2 15
2 15 | 9 | 6.3 | 10 | | | |
 | : |

 | •
 | | | - | P.R.
 | | PAP | 1 SK | | | | | | | | |
 | | |
| 9 | õ9 | 69 | 9 | 9 6 | 2 | 9 | ;
; | | | ec. + |
 | |

 | į
į
 | | | | 5
 | | = : | 0 | |
 | • | |
| į | | : | | | į | | 50 | 35 | 5 | 4 | 9
 | 20.0 |

 |
 | | • | | |
 | | | | |
 | | |
| : ID | - | :
و | n i | e e | | *2 | 160 | | ľ | 3 1 6 | 7 10
 | <u> </u> |

 | İ
 | | | | الا
0
 | | 2 | 8 | | :
 | | |
| | 0A. | 07. | 6 | 96 | 90 | 96 | 7 | | 1 | |
 | |

 |
 | | <u>د</u> ۲ | | ١
 | X | - | 6 | | :
 | • | |
| 9 | 9 | ಲ | 9 (| ø « | 2 | £ | Œ | | ا و | S 4 | ,
 | |

 |
 | : | 70 | ш | وابي <u>ا</u>
 | <i>U</i> , | | اه يو | |
 | | |
| ì | | | | | | | 2 | 121 | | • | 000
 | 373 | 40

 |
 | | Z. | 106 | IV
 | 787 | SAR | 186 | | :
 | 5rL
500 | |
| 9 | . 2 | 1.1 | ? | 6 4 | | £ . | 2 | | | ¢ | u ' '
 | 1 | IGE

 |
 | : | MA | BR | -
 | <u> </u> | Z | ₹ 0 | | !
 | 18 | |
| 0 | 9 | 9 | 3 | 9 6 | 3 | 9 | | | | . |
 | | TOR.

 | İ
 | | 100 | RD | ,
20
 | 7. A.R. | 2 S | 90 | | :
 | • | |
| ! | | 1 | | | ĺ | | 100 | 47 | 9 | 0 • 0 | 2
 | | (

 |
 | | | Z |) <u>.</u>
 | | (a) | 5 | |
 | NTH
37. | |
| _ | ۳, | _ | ~) (| ی ج | | N. | 15 | 2 | 7 | | , 6
 | 100 | 5

 | i
 | | I | 166 | - ;
 | ~ | | } | | | | | | | | |
 | - - - | i |
| | 0.8. | 01. | 97. | . 4
. 4 | 90 | 90 | l | | | |
 | | A X 1

 |
 | | | , |
 | | 00 | 20 | | i
 | ** | |
| 9 | • | 9 , | ۰ | ک ع | 9 | ت | × | • | , e | |
 | 1 | =

 |
 | : | | UL S | 100
 | | 4 . | NS T | | 1
 | 1 E | |
| ! | | | | | | | 9 | A 56 | 2 | |
 | ! |

 |
 | : | | 9 | į
 | | | - | • | i
 | 1 | |
| | | 1.0 | | | 100 | 6.3 | | - | | |
 | i |

 |
 | | : | OH- | 1 A O
 | | 300 | 20 | | i
 | | |
| 7 | 401 | 69 | 9 | 200 | 200 | 9 | • | ₩. | <u>.</u> | <i>.</i> . • | c
 | |

 | †
!
 | : | | 9 | 15
 | | 12. | S S | |
 | : | |
| | | | | | 1 | | | ű | Š | i i | Ē .
 | | į

 | ļ
 | | | ITIA | ,
 | | i, | ł | |
 | - | |
| ~ | Š | œ | ~ (| 2 ~ | | ₩. | | | | 2 | 4
 | JS (|

 |
 | | : | ROC |
 | | 0.0 | 1 | | 1
 | £ 99 | |
| 10. | 08. | 07. | ç | | 90 | 90 | | | ! | |
 | HOH | į

 | •
 | | | בר |
 | | ಕ | ! | | 1 K
 | . 0 M | |
| ت ا | 9 | ¢ | ، ت | E (| *** | 9 | | | i | |
 | - | ļ

 | 15.
 | : | | Z |
 | | | 1 | | 100
 | | |
| | | | | | i | | | | • | |
 | | 1

 | . 9
 | | | H) | | | | | | | | |
 | | | ; | |
 | . (2) | |
| - | 9.6 | 6. | • | | 1 | 5.0 | | | • | |
 | | :

 | •
 | | | : |
 | | | 1 | | 17651
 | S . | |
| 2 | 9 | 9 | 9 | 2 | 60 | 909 | | | | |
 | |

 | 13
 | : | | |
 | | | | | Ä
 | | |
| | | | | | ; | | | | : | |
 | | i

 |
 | | | |
 | | | : | | Ŧ
 | 110 | |
| | | | | | 1 | | | | : | |
 | | 1

 | STA
 | ı | | |
 | | | į | | 1
 | . S. O. | |
| | | | | | | | , | | 1 | |
 | | •

 |
 | í | | į | | | | | | | | |
 | | | i | |
 | : | |
| | | | | | i
I | | | | ٠ | |
 | | 1

 | - E
 | : | | |
 | | | ! | | FF
 | ì | |
| i | | | | | 1 | | | | i | |
 | i | 1

 | 1
 | | | : |
 | | ! | . i | | Ē
 | 1 | |
| | 610-4 610-4 610-1 609-8 609-3 609-3 609-9 608-8 | 610-7 610-4 610-1 609-8 609-3 609-3 608-9 608-8 608-5 608-5 608-5 608-1 608-1 608-0 608-0 607-9 | 607.9 607.8 607.7 610.4 610.7 607.6 609.3 609.3 609.1 608.0 607.9 607.9 607.9 607.5 607.5 607.5 607.5 | 610-7 610-4 610-1 609-8 609-3 609-3 609-1 608-9 608-8 607-9 608-9 607-9 607-9 607-9 607-9 607-9 607-9 607-9 607-9 607-9 607-9 607-1 607-9 607-1 607-1 607-1 607-1 607-1 | 608-6 608-5 608-4 610-4 610-4 600-3 609-3 609-3 609-3 608-8 608-8 608-6 608-9 608-9 608-8 607-9 | 608.5 608.5 608.2 608.1 608.1 608.1 608.1 608.0 607.9 608.8 608.1 608.1 608.0 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.0 | KII.1 GIO.7 GIO.4 GIO.4 GOR.2 GOR.1 GOR.1 GOR.0 GOR.0 GCR.6 GCR.6 GCR.1 GOR.1 GOR.1 GOR.0 GOR.0 GOR.0 GCR.6 GCR.6 GOR.1 GOR.1 GOR.0 GOR.0 GOR.0 GOR.7 GOR.7 GOR.0 GOR.0 GOR.0 GOR.0 GOR.9 GOR.0 GOR.0 GOR.0 GOR.1 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR.0 GOR | 608.6 608.5 608.8 608.2 608.1 608.1 608.0 607.9 608.8 607.9 608.0 607.9 608.0 607.9 | K11.1 G10.7 G10.4 G10.1 G09.8 G09.5 G09.3 G09.1 G08.6 GCR.6 GCR.6 GCR.1 GOR.1 GOR.1 GOR.0 GOR | K11.1 G10.7 610.4 610.1 G09.8 609.5 609.3 609.1 608.6 6CR.6 6CR.6 6CR.1 6CR.1 6CR.1 6CR.0 6CR.0 6CR.0 6CR.6 6CR.6 6CR.1 6CR.1 6CR.0 6CR.0 6CR.0 6CR.6 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 6CR.0 | 608.5 608.5 608.2 608.1 608.1 608.9 608.8 609.1 608.0 608.0 607.9 608.0 608.0 607.9 608.0 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.0
607.0 | 608.5 608.5 608.2 608.2 608.3 609.3 609.9 608.8 607.9 608.0 607.9 608.0 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.9 607.0 | KII.1 (II.7 610.4 610.1 609.2 609.3 609.3 609.3 609.3 609.3 609.3 609.3 609.3 609.9 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 607.1 607.1 607.1 607.1 607.1 607.1 607.1 607.1 607.1 607.1 607.1 607.1 606.5 606.5 606.5 606.5 606.5 606.5 606.5 606.5 606.5 606.5 606.5 <th< td=""><td>606.5 608.5 608.4 610.1 609.2 609.3 609.3 609.4 608.0 607.9 608.8 608.6 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 607.0 607.9 607.0</td><td>CONTRACTOR CONTRACTOR /td><td> Color Colo</td><td>CONTRIBLE CONTRIBLE ><td>(CONTRINED FOR EACH CANANEL ROUTING -400 CONTRACT CANANAWAY NAVINGE FOUNDED FOR EACH CANANAWAY STACE IS GIVEN CANON CONTRACT CANON
CANON CANO</td><td>CONTRIBUTE FOUR FOUR TIME CHANNEL ROUTING CONTRIBUTE CO</td><td> CONTRINGED CONTRICT CONTRIC</td><td>CONTRIBUTION STAFF TO THE TOTAL CONTRIBUTION OF THE TOTAL CONTRIBUTION</td><td>CONTRICT CONTRICT td>CONTRACTOR CONTRACTOR /td><td>CONTRICT COLUMN</td><td> COLUMN
COLUMN C</td></th<> | 606.5 608.5 608.4 610.1 609.2 609.3 609.3 609.4 608.0 607.9 608.8 608.6 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 608.0 607.9 607.0 607.9 607.0 | CONTRACTOR | Color Colo | CONTRIBLE CONTRI | (CONTRINED FOR EACH CANANEL ROUTING -400 CONTRACT CANANAWAY NAVINGE FOUNDED FOR EACH CANANAWAY STACE IS GIVEN CANON CONTRACT
CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CONTRACT CANON CANO | CONTRIBUTE FOUR FOUR TIME CHANNEL ROUTING CONTRIBUTE CO | CONTRINGED CONTRICT CONTRIC | CONTRIBUTION STAFF TO THE TOTAL CONTRIBUTION OF THE TOTAL CONTRIBUTION | CONTRICT CON | CONTRACTOR
CONTRACTOR | CONTRICT COLUMN | COLUMN C |

			:		:				-		3
STORAGE	0.00	• 05	* O *	. 05 55	.07	.03	1115	1.32	1.54	1.16	
OUTFLOV	0.00 2A22.73	75.40	7840.44	445.72 11378.37	701.81 17014.55	993.28 23930.22	1314.49	1661-12	52446.32	2417.75	. i. i. i. i.
STAGE	605.00 611.84	605.6R 612.53	606.37	607.05	607.74 614.58	615.26	609-11	616.63	610-47	611.16 612.00	
FLOV	0.00	15.40	232.06	11378-37	17014.55	993.2R 23930.22	1314.49	1661-12	2029-79	2417,75	(14. <u>±</u> 2.)

	<u> </u>		-			^			7			_	· ·		<u> </u>	33	,	•		~ 	-	_	<u> </u>		\ 	T.E	•	-	•	<u>`</u>		(<u> </u>		() []			5		•		(Ð		ē	<u> </u>
		109					;																					•			<u>;</u>				1												
	•															:															:																
																																					:								1		
1			, !				:				:			:		1								:		1.		;			:		:				!			;							
1-		¥	· «	10.		133.	686.	.91.	83	87	30.		30.			29.	21.		; .o	•	•	• -						•		• •	•	•	•			5.0	1.5	٠.	5.1		6.3		•	•		تر الله الله الله الله الله الله الله الل	•
1						- •	;	10 j	B	3 6	1	•		•										† 1									:		į	9	9	9	9 4	, ,	. 9	9	7	3		, O C	2
I		•	; . .	. 5	13.	103	467	3167	6827.	2976	2	2	139	; -	46.	30.	22.		•	•		• •			•			.					•	:		ŝ	ıÖ:	٠. د	ů	ė e		:		'n.	• •	608.7	•
1				• •				_			1		. •	•		•						•											•		}	0	;			:							
1.			_	9, 5	12	46	29.5 39.5	3043	5992	3266	1241	513	147	-	4	31	23			0	0	- c	•		<i>-</i>	-	• •	0	.	-	0	0	- -		į	605.	605.1	605.1	605.1		606	606.	612.	613.	612	, 60 %	
*	.0 3	-	: ;, :	19.	::	Q. F		-	- 4	. =	5	8	3.0°	. 8	51.	33.	23.		•			•							• •	• •			• •			5.0	ŝ		Š	• •			:	٠.	• •		•
1	W .		:			•	- 60	53	53	. 10	13	en e	~ -	•					ļ					•				!								9	09	9 (\$ G	200	9	9	61	3 ;	: 3	200	Ī
I	LAN	•		• •	::	72.	307	0	4755	ຳຫ	•	603.	296.		. 53	34	24.			ċ	•	• •		•	•		:	•	•		•	<i>:</i> .		:		05.	95	5	95.	9	96.	90	1.	2:	2.5	609	•
7	12,1	OUTFLOW				•								-				108		•		• •							•			•			7 A GE	6	-	 ,	 .	- u	, o	.		v.		, - .	ع
	A	ລິ	21.5	6 C	-	9	283		4.0 4.0 4.0		•	629	177	76	56	35	25	40	0	0		.	•	0	-			0	0	- 0	0	0 () 		60	05.	05	95	65.0		96	90	=	5:	3.6	0000	:
	3	٠.	•		90	-	9.4	ю.	~ 5	· œ	6	- 1	? 🗷	0	S	37.	25.		•	•	٥	• •		0.	•			•	• •	• •	•	ė,	•	:		ŝ	ŝ,	ů.		 		٠	-	ů.	;	0.0	:
•	TATION					•	2	~	0		17	~ 1	∘ -	-					1																	6.0	09	5.0	3 4	209	09	90	6.1	;	2,E	7 5	2
•		•	: :	œ ç		F1 6	253	196	8	. E	5	5	200	60	3	39	Ġ		•	•	•	• •		•	.	-		•	.	• •	0	•	.	6		ŝ	ů.	ŝ		•		2				610.4	:
•	:		•	•		•		•	•			•	•			•						•										•	•				!								1	α.	
· .	:	•	- c.	æ <u>=</u>	2 -	O. F	240	5.0 A	30	0	202	£ 1	25	2	5.	0	27		0	0		>		0	0		6	0	0	> C	0	0	5 C	•		S.	Š	ů.	ů,	n n			9	÷ 5	•	410	•
		•				16.	26.	0	E 4		£.	0	~ •	•	5	2	Œ		•	•		•			•		•		.	•		•	•	•		5.0		•			• •		•	•		2.5	٠
į					_	;	~ ~	0	*	-0	•	š :	• 6	-	_	. !	- •														:				:	609	604	905		> Y	605	909	ę			555	Š
1			!								!					;										:					1						,			1					;		
E	, 1 1		:											! : 1		i			!									1			}						ı										
I			1	<u></u>	-		<u></u>	·	•			Ξ,		-	<u> </u>	Ŧ	Ξ,	<u> </u>	<u> </u>	Ž	<u>. </u>		i i	1	K .	1		-	Σ,	7	1	r.	ΕĖ	<u>.</u>	\$ \$			1	<u>.</u>		Ì	_ <u>i</u>	Ā			<u></u>	Ē

0 ·	6-90	6.06.8	606.A	606.7	606.6	-		16.5	£06.5	606.4	606.4) :	
	٠.٠	6.06.3	2.909	£0£•2	606.1			0.9	0.909	606.0	6.05.9			<u>_</u>
	05.9	405.9	605.8	605.B	6.05 B			15.7	605.7	605.7	6.05.7			<u> 510</u>
0.9	95.6	605.6	605.6	605.5	605.5			5.5	605.4	605.4	405.4		!	=
99	15.4	4.05.4	605.3	6.05.3	605.3	_		5.3	605.3	605.3	605.3			<u></u>
	605.3	£05.2	605+2	605.2	605.2	605.2		. 2.509	605.2	605.2	605.2	1		Ξ.
			3.6	H-3		24-HOUR	72-H0UR	TOTAL	VOLUME					_
		CF		52			1154.	N	30863.					· ·
	•	CHS	! !	243. 14	1	i	33.	! !	6537.					
		INCHE		9.	15		11.26		11.26					
		Ī	T	232.	~	285.27	285.89		285.89					
:		AC-F	_	258	•	3173.	3180.		3180.	:				·
		THOUS CU M	£		06	3914.	3922.		3922.					^
								!						
	,			MAXIMUM	STORAGE	41	•			!				^
														7
MANIMUM STAGE 1S		613.5												\ ! =
	!											: :: : : : : : :		

0 9 0 9	605-1	105.2 605.9	605.3	605.4 F06.9			605.6 606.1	605.7	605.8			ກ.ດ ຄ.ຄ		
109	606.3	605.4	606.4	606.5			9.909	2.959	6.909					,
£0.5	608.0	608.7	609.4	609.9		61	10.9	61164	611.8			1.2		
	613.4	613.4	613.5	613.4	613.4		1304	613.3	613.2		1 613	, E		
9	613.0	(12.9	612.A	612.7	i :	:	612.4	612.2	612.0			1.1		
01.1	7.0	f10.2	4.09.7	6.09.3			6.08.5	608.2	60R.0	6.07.8	.8 607	9.1		
9	607.4	607.3	607.2	607.1	09		6.909	6.909	606.8	,	•	606.7	:	
0.9	9.909	606.6	606.5	606.5			06.4	606.4	606.3			2.9		
£04	604.2	£06.2	606.1	606.1			0.90	606.0	606.0	602.9		5.9		
-04	605.9	505.8	605.8	605.8			605.7	603.1	605.7	605-6	602	3.6		
200	663.0	600 600 600 600 600	6000	600 Pe	6000	F #3	605.2	605.2	605.2	605.2		0.00		
09	605.2	605.2	605.2	605.2	0	2	ŕ	605.2	605.2	6,05		5.2		
			74	٠	-HOUR 2	-	72-H0UR	IR TOTAL						
		ن :	CFS R5	5.		- 1		:	~		:	:		
		,			146.		31.	•	6201.					
		INCHES	S #	ć	9.03	10,65	10.6	ھے س	10.68					
	:	AC-FT		3	2552	3009	3016	•	3016					
		THOUS CU	· x .	•		3712.	3720.	•	3720.					
MAXIMUM STAGE IS	19	613.5											,	· · · · · · · · · · · · · · · · · · ·
1 de 1 de 1 de 1 de 1 de 1 de 1 de 1 de	***************************************		***	•	• • • •	******		***	•	****			!	:
		:	}		HYDROGRAFH ROUTING	IFH ROUT	ING	:		:	•	:		
	CHAI	CHANNEL ROUTING	00 H-	PULS- REI	ACH 5									
	:		1STAG A13	ICOMP	JECON	IT APE	JPLT	JPRT	INAME 1	ISTAGE	TAUTÔ 0			
		:	!		ALL PLANS ROUTI	PLANS HAVE SI	AME	:		:	!		,	
		0000	CL 055	AVC 0.00	IRES	ISAME	1001	IPMP		LSTR			!	:
					' '		;	i						
		:	NSTPS 1	NS TOL	0 P	AMSK.K 0 • 00 0	0.00.0 0.00.0	1SK 0.000	STORA 1	I SPRAT 0	;	:	1	
						1				:	;	1		
MONTAL DIVIN CHENNEL FOOLING	VME L MOC	5F 1 - 0		1	:	•								
00013	0H(2)	0N(3)	ELNVT			SEL								
	.0500			:	200°	11600								

Ð.

•

6 0

THE PERSONS

حتت	<u> </u>		JJI	الله قد الـ	
ا ان = :	83.50 83.50	1713-15	565.68 572.00	1713-15	
	5.07	1269.77	565.05	11104.22	
	3.83	915-29	554.42	915.29	
560.00	23.11	639.79 8031.60	563.79 570.11	8031.60	
.00.118.00	1.94	6728.65	563-16	432.60 6728.65	
100.00 560	1.33	5571.77	562.53	5571.70	
14 ELEV-ETC 1.00 562.00	14.70	1	561.89	173,31	
567.00 100 516	12.63	366.62	561.26	Ì	
1 COORDINATES	15.	, 6	560.63	N .	
CROSS SECTION COORDINATESSTA-ELEV-STA-ELEVETC 0.00 572-00 118-00 560-00 0.00 572-00 560-00 180-00 560-00 560-00 560-00 560-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00 572-00	00.0	ים יכ		0.00 0.00 2254.62	
:	STORAGE	OUTFLOW	STAGE	AC74	

SALAN WATER

6.

_		70.3	570.3	5.10.2	5 70.1	56.6	240.7	569.5	569.3
		F.B.7	. 4.89%	5.6P • 1	567.8	567.6	567.3	567.1	3.495
,		66.1	₹65.B	565.6	565.4	5.65.5	565.1	564.0	564.7
	ŀ	2.4.5	564.0	563.9	\$63.7	563.6	563.4	563.3	563.2
563.1 563.0		562.9	562.B	562.7	562.E	562.5	562.4	562.4	562.3
		52.1	562.0	561.9	561.9	561.8	561.7	561.6	561.6
		61.4	561.4	561.3	561.3	561.2	561.2	561.1	561.1
		F1.0	560.9	560.9	560.9	560.9	560.8	3.098	560 . R
_		10.1	560.7	560.7	560.7	560.7	560.6	560.6	560.6
	, I	9.09	560.5	560.5	\$60.5	560.5	560.5	260.5	560.5
		PEA				UR TOTAL			
	CLS	#564	5214.						
	SHO	242	_			3.	6537.		
	INCHES		9.15	11.23	11.25	25	11.25	:	
	£		232.			187	285.87		
	AC-FT		258			• 0.	3140.		
OH.	HOUS CU F		318	į	į	.2.	3922.		:

MAKIFIUF STAGE IS 570.3

7 2

FOUTED TO 111 5.33 1 2000 1 20		<u> </u>				<u> </u>	CI.	EEEE.	E E			C Eest	.	्र । 121	.	<u>.</u>
1 5.16 1 6.17 1 1 1 1 1 1 1 1 1	310	1	i		:	! !	:			i	,	!	:			
1 5.16 1 6.17 1 1 1 1 1 1 1 1 1	7	, i				;	i		,	; ;		1	:			
111 5.30 1 2407 1 120.291 1 13.73				:	1	!	İ			:	!					
111 5.30 1 2407 1 120.291 1 13.73				· ·	;				÷			•			;	
111 5.30 1 2407 1 120.291 1 13.73		:		1						•	:	: i		: :		
111 5.30 1 2407 1 120.291 1 13.73					i						1		; }) ,		
111 5.30 1 2407 1 120.291 1 13.73							1 1			1	•	!	!	ı		
111 5.30 1 2407 1 120.291 1 13.73		:	1						:				:	}- -	:	
111 5.30 1 2407 1 120.291 1 13.73							Ì		; f		! !	1	:	(: :	
111 5.30 1 2407 1 120.291 1 13.73		•	i						:	<u> </u>	į	1		:		
111 5.30 1 2407 1 120.291 1 13.73			i	;			į		:		: :	1		, !		
111 5.30 1 2407 1 120.291 1 13.73		; ;					ĺ		: ! !		<u>{</u>					
111 5.30 1 2407 1 120.291 1 13.73							Ì	1					•	!		
111 5.30 1 2407 1 120.291 1 13.73		ĺ	i						.			i i			•	
111 5.30 1 2407 1 120.291 1 13.73				1 1			İ					1				
111 5.30 1 2407 1 120.291 1 13.73		:							:		: •	İ	:	i		
111 5.30 1 2407 1 120.291 1 13.73		!	:							† i	:	1		:		
111 5.30 1 2407 1 120.291 1 13.73		•									:	}				
111 5.30 1 2407 1 120.291 1 13.73		;														
111 5.30 1 2407 1 120.291 1 13.73	J				+					1	} :		: !	!		
111 5.30 1 2407 1 120.291 1 13.73	56.5	575 73) 566 57)	57.3	2000				,	į })) i	}	ļ			
111 5.30 1 2407 1 120.291 1 13.73	8 2 2	2 2 3	2 2	E 018 0]								: '	
A11 5.30 1 20070 A12 5.30 1 20070 A12 5.30 1 20070 A13 5.30 1 20070 A13 5.30 1 20070 A14 13.73			1	1 1											:	
A11 5.30 1 20070 A12 5.30 1 20070 A12 5.30 1 20070 A13 5.30 1 20070 A13 5.30 1 20070 A14 13.73	29)	25.	246	293									<u>.</u>			
A11 5.30 1 20070 A12 5.30 1 20070 A12 5.30 1 20070 A13 5.30 1 20070 A13 5.30 1 20070 A14 13.73	120	120	113	120							} !				! ;	
A12 5.30 1 6.30 1 6 6.30 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		-		_11					}				<u>;</u>			
A12 5.30 1 6.30 1 6 6.30 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	62.	52	62.0	140 599			}						i i 1		Ì	
A12 5.30 1 2 4 1 1 1 1 1 1 1 2 5.30 1 1 2 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.	2397	218	25.			Ì		!				İ		: }	
A12 5.30 A12 13.73) A13 5.30 A13 5.30 A14 13.73)	_]				į		: i	ļ		
	~	- 2	- 6	-			1		ĺ		•		i		•	
							1					1		<u>.</u>]		
		30	800	30					! ;				:			
		3.7	S. 5.	3.7			Ì		i				:			
		! -		1 (ļ.	,	1		<u> </u> 		
		=		2			;		t			!				
10 TED TO 10 TED		. •	∢ . ;	«) 1		1			} }		:		,		
10 10 10 10 10 10 10 10 10 10 10 10 10 1		:	i i	;	;	<u> </u>				1		:				
01 TED TO 10 TED		1		ļ		; ; ;			•	į		} ;				
O TEO		10	2	-		1 :	!			•		:		İ		
		jteo	ŲTĘŪ	J7EP	1				,		r	!				
		2	5	20.2	<u> </u>				ì	!	;	1		1	; ;	

SUHHARY OF DAM SAFETY ANALYSIS

		•						ı									
	TIME OF FAILURF HOURS	15.83 14.17 13.50			TIME OF FAILURE HOURS	00.0	000										
OF DAM 673.20 106. 239.	TIPE OF MAX OUTFLOW HOURS	2 6 6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	TOP OF DAM 673.20	239.	TIME OF HAX OUTFLOW HOURS	17.33	17.33	;		i :							
106	DURATION OVER TOP HOURS	5.46 5.19	št tep	:	DURATION OVER TOP HOURS	4 . 33	9.50	ÀS	TIME	16.83	17.33	A 3	ŤÍME HOURS	17.33		TIPF	16.83
SPILLWAY CREST 649.00 60.	MAXI MUM OUTFLOW CFS	1192. 1945. 3910.	SPILLWAY CRES 669.00 60.	•	MAXIMUM OUTFLOW CFS	175.	3910.	STATION	MAXIMUM STAGE .FT	668.6	669.8 671.9	STATION	HAXIMUM STAGE . FT	6.67.7 6.69.8	4102	HANTPUP	679.2 670.1
:	MAXIMUM STORAGE AC-FT	108. 111. 128.	;	.01	MAXIMUM STORAGE AC-FT	114.	139	PLAN	HAX IMUN	1190.	1946. 3911.	PLAN 2	FLOVICES	775. 1957. 3911.	·	<u>ہ</u> ۔	1180.
INITIAL VALUE 670.00 10.	MAXIMUM DEPTH OVER DAM	1.62	INITIAL VALUE 670.00 70.		HAXIFICH DEPTH OVER DAM	.61	7 - C	IC.	RATIO	• 10	 		RATIO	.10 .25	. <u>4</u>	PATTO	.10
ELEVATION STORAGE GUTFLOW	PAXIMUM RFSERVOTR V.S.E LEV	673.35 673.60	ELEVATION STORAGE	outs Lov	MAXIMUM RFSERVOIR V-S-ELEV	673.81	675.60		•								
	RATIO OF DRF	• 255 • 255 • 255			0 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	.10	04.			!			:				
F F 8) P. P. P.														

						•			
17.33		11MC HOURS	17.33 17.33 17.33		†1ME HOURS	17.00 17.50 17.33		T I MF HOUR S	17.50 17.33 17.33
	4			A 5		:	A 5	_ :	
671.3	Statiny	MAXIHUM STAGE+FT	66801 67001 67103	STATION	MAXIMUM STAGE+FT	640+3 641+3 642+9	STATION	MAXIMUM STASE+FT	639.7 641.3 642.9
3911.	FLAN 2	FLOU _T CFS	1954. 3911.	PLAN 1	MAX IMUM FLOUICES	1121. 1939. 3906.	PLAN 2	MAX IMUM FLOW+CFS	772. 1949. 390A.
• 50	14	RATIO		ਂ ਫ :	RATIO	.25	14	RATIO	•10 •25 •50
		:		•			:		
	;		•		; ;			1	
					•		;		

SUFFARY OF DAM SAFLTY ARALYSIS

							1								
			٠	:			!		;		•			•	
	TIME OF FAILURE FOURS	15.67		• . •	TIME OF FAILURE HOURS	0.00	1		1	:	1	•	:		
TOP OF DAM 637-10 197- 4P3-	13PE OF MAX OUTFLOW HOURS	16.67 17.33	OF DAN 637-10	197.	TIME OF MAX OUTFLOW HOURS	17.33 17.17									
	DURATICN OVFR TOP HOURS	2.92	100		DÜRATION OVER TOP Hours	7.50		TIME	16.67 17.33 17.17	49	TIME	17.33		11HE HOUPS	16.67
SPILLUAY CREST 634.90	MAXI PUM OUTFLOW CFS	2504. 4171. 8572.	SPILLWAY CREST	155.	HAXINUM OUTFLOW CFS	1462. 4256. 8569.	STATION	MAXIMUM STAGE+FT	616.9 618.4 620.6	STATION	PAXITION STAGE +FT	6114.0	MOTTATO	1 PUR E + F T	615.5
VALUE 90 55 -	MAYIMUN STORAGE AC-FT	201.		155.	MAXIMUM STORACE AC-FT	223.	PL AN 1	HAXIMUM FLOH+CFS	2918- 4170- 8571-	PLAN 2	HAXIMUM FLOW.CFS	1662. 4748.		PAXIMUM LOV-CFS	2417. A171.
•9 •951 06•969 06•969	FAXIHUM LEPTH OVER DAN	.21 2.78			MAKINUM DEFTH OVER DAM	2012	14	RATIO	.10 .25 .50	14	RATIO	- C L	2	RATIO	. 10 7.10
ELEVATION STOFAGE OUTFLOW	RESERVOIR W-S-LLEV	637.31 637.69 639.88	FLEVATION	OUTFLOV	HAXINUM RESERVOIR W.S.ELEV	638-27 639-82 641-57		:					:		
	RA110 0f 0f 7MF	6 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6			0114 & C d	.10	•								
7. 4.			FLAN												
												•	1		

17.17

8570.

.59

RATIO FLOW-CFS STAGE-FT 615-1 -10	RATIO FLOW, CFS STACE, FT -10											÷					•										
RATIO FLOW-CFS STAGE-FT -10 1662- 615-1 -25 8565- 617-5 -10 2407- 611-3 -27 8512- 613-0 -10 2407- 611-3 -20 8567- 613-0 -20 8507- 613-0	### ### ##############################	TIME	17.33	17.17	17.17		TIME	HOURS	16.83	17.33		_	116	H 00K S	17.33	17-17		TIME		17.17	•	Ţ Î ME HOURS	17.33	17-17	_	11ME HOUPS	16.83
RATIO FLOW-CFS - 525 - 424 R 50 - 424 R 50 - 424 R 50 - 424 R 50 - 4170 - 550 R-	######################################	HAXIMUR STAGE .FT	615.1	616.2	617.5			STAGE OFT	6111.3	613.0	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		HINAIX WI	SI AGE OF I	610.5	415.4		MAKIMUM STAGE +FT		612.5 613.5	A	. •	4.609	6174.0		MAXIMUM STAGE OF T	566.5
TIAN SEC. STAN SEC. SEC. SEC. SEC. SEC. SEC. SEC. SEC.	RATIC ************************************	HAXINUM FLOW,CFS			8565.	-		FLOWCFS	2407.	4170.	9150	~	MUMIXAM		1662	8566	-	MAY IMUN FLOV-ČFS	i	8573	; ~		i 66.2.	P.5650		rax I w UM F L CW + CF S	2440.
		RATIO		!	98.	14	-	RATIO	:	8. E	06.	!	4		.10	0.5	14	RATIO	710	. 50	PL		• 1 0 2 c		14	RATIO	.10

7				L. X.ET.	727	tor.v		<u> </u>	TLUE	13.53	A.J.			EEEE!	נווינו		e (Eleb)
130																		
-																		
										* * * * * * * * * * * * * * * * * * *								
										1			,		•			
			·			!		!										
			•	i		•	•	!			•	;						
								,		!				·				
			•			1	,	:				t		:				
			1	:		:		i			•	!		i				
					ı	i	•	į		i	:	; 1						
17-17		F.S.	10 10 to															
17.		TIME	17.33 17.33 17.17			ı						•		:				
	A13	2 L	90n			:		:		•		1	;	;				
570.3	NO.	HAXIMUP STAGE .FT	565.6 568.0 570.3	•		:	;	:						i				
	STATION	E.V.	;	;		!	i	i	:		- :	!	,		i	• :		
•		FS	1659 424 R 8554	:	:			.				1	٠			i		
₽26.	~	MAX IMUM FLOW+CFS	88.5				! !				:					1 1 1	•	
	PLAN					!			:		1						1	
•50		Ĩ 10	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		;								i			:	i !	
		: ≪ :ær							:								:	
					!			[!				:				•	
			!		•			1	;		,					; •	•	
	1					i !		•	•					:				
	!			i	•		:							!				
				i	1	1	:		,	1				:				
	i		•	:			1	•										
										•								
										-								
				•		,												
			•													•		
			i	į	:					;								

2.50

このとの「不らの間を中央として、それにより、まないのは、これをはなっているのでは、これにはないのではないのできないのできないとうことになっている。

APPENDIX 4

REFERENCES

LAKE AMES DAM

APPENDIX 4

REFERENCES

LAKE AMES DAM

- 1. Chow, Ven Te, Open Channel Hydraulics, McGraw Hill Book Company, New York, 1959.
- 2. King, H.W. and E.F. Brater, <u>Handbook of Hydraulics</u>, McGraw-Hill Book Company, New York, Fifth Edition 1963.
- Schway, G.O., R.K. Frevert, T.W. Edmister, and K.K. Barnes, <u>Soil and Water Conservation Engineering</u>, The Ferguson Foundation Agricultural Engineering Series, John Wiley and Sons, Inc., New York, 1966, 683 pp.
- 4. U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1) for Dam Safety Inspections Users Manual, Davis, California, September 1978.
- 5. United States Department of Interior, Bureau of Reclamation, Design of Small Dams, U.S. Government Printing Office, Washington, 1977, 816 pp.
- 6. U.S. Department of Interior, Geological Survey, 7.5-Minute Series (topographic) maps, scale 1:24000, Contour Interval 20 feet: Dover, N.J., (1954), Boonton, New Jersey, (1954).
- 7. U.S. Department of Agriculture, Soil Conservation Service, Urban Hydrology for Small Watersheds, Technical Release No. 55, Washington, 1975.
- 8. U.S. Department of Commerce, Weather Bureau, "Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1000 Square Miles and Durations of 6, 12, 24, and 48 Hours", Hydrometeorological Report No. 33, Washington, 1977, 816 pp.
- Lewis, J.V. and H.B. Kummel (1910-1912) Geologic Map of New Jersey, revised by H.B. Kummel, 1931, and by M.E. Johnson, 1950, New Jersey Department of Conservation and Economic Development Atlas, Sheet 40.